EXHIBIT 4 Deferred Maintenance Items and Budget Terminal/Offices and Hangars 2, 3 and 4

Items	Budgetary Cost
Terminal/Offices: All rain gutters and damaged siding panels. Repair offices roof damage if any. (Not visible) Anchor A/C condensers to the slab.	TBD TBD TBD
<u>Hangar # 2:</u>	
Structural Condition Assessment Report -Replace all gutters and trim -Replace Base Angle -Repair/Replace Bottom Wall Panels -Replace Rolling Doors -Clean and Paint Structural Framing (floor to ceiling) -Structural Framing Repairs	\$12,000 \$1,200 \$3,600 \$8,000 \$15,000 \$4,000
Walk Through Inspection -Remove wild palm tree in parking lot and building siding panels -Repair hangar roof including officesCorrosion control and paint hangar doors track railingsReplace/paint all damaged side paneling floor support railingsReplace all damaged panels between Dan GSE / Ocean Air and hangar. (Damaged at floor)	TBD TBD
Hangar # 3 & CCSA:	
Structural Condition Assessment Report -Replace all gutters and trim -Replace Base Angle -Repair/Replace Bottom Wall Panels -Replace Rolling Door Tracks -Repair Rolling Doors -Clean and Paint Structural Framing (from floor to ceiling) -Structural Framing Repairs -Fire Line Riser Repairs	\$18,900 \$1,600 \$2,400 \$12,000 \$12,000 \$19,000 \$12,000 \$8,000
Walk Through Inspection -Repair hangar roof including officesAll doors and hinges need paintingAnchor A/C condensers to the slab -Corrosion control and paint all side paneling support railingsReplace and paint all damaged side paneling floor support railingsReplace all stained ceiling tiles in office area 1 st & 2 nd floorsRepair and paint all damaged drywall in office area 1 st & 2 nd floors.	TBD ors, TBD
-Repair Janitorial door and trim.	TBD

EXHIBIT 4

Deferred Maintenance Items and Budget Terminal/Offices and Hangars 2, 3 and 4

-Repair or replace ceiling insulation at Civil Air Patrol offices.	TBD
-Replace lighting covers on light fixtures in offices and hallways.	TBD
-Replace all broken exterior light covers.	TBD
-Remove all wild growing plants that are not maintained.	TBD
-Fire Sprinkler header needs corrosion control, backflow device	
and bollards installed.	TBD
-Comply with NFPA 409 for Group II Facility pertaining to sprinkler	
System requirements	TBD

NOTES:

All Budgetary cost are estimates provided by PGAL Engineering at the time of Structural Condition Assessment. The Director or his designee will approve repair workmanship for all items.

ltems corresponding to PGAL Structural Condition Assessment report are appended to this Lease as

Exhibit 3.

Walk Through Inspection items were identified and agreed to by Lessee and Lessor as needing repairs or replacement.