Hygeia Office Deterioration


May 21, 2024



The Issue

- Building has interior deterioration
 - Sinking Floor
 - Interior walls separating from ceiling
 - Trip hazardous
- Current space is too small to accommodate the staff managing waste collection operations at the administrative office
 - 50+ drivers dispatch from current offices
 - 6 additional staff located in additional areas will join






Interior Wall Example

 Multiple interior walls separating from ceiling.






Trip Hazards

•Floor sinking creating separation from stairs.





Exterior Door

 Exterior door wall is sinking causing potential egress issues.



Lease vs Purchase Options

Average Lease cost per year*

\$ 88,590

Delivery time**

1 month

Purchase cost

\$317,817.14

Delivery time**

5-6 months

 The purchase of the modular building was unbudgeted for FY24 but proves to be the most cost-efficient option between the two.

Break even at 3.7 years

*First year is higher due to front loaded cost

**From date of order

