## Capital Improvement Plan

# City of Corpus Christi, Texas

Project # 21031

**Project Name** Storm Water Pipe Inspection

Type Reconditioning-Asset Longevity

Category Storm Drainage

Useful Life 10 years

Department Public Works- Storm Water
Contact Director of Public Works

Priority 2 Critical- Asset Condition\longevity

ROOF DRAWN
UNCAPPED
CONNECTION
UNCAPPED
CLEANOUT
UNCAPPED
CLEANOUT
ROOT INTRUISION
INTO LATERAL
POUNDATION DRAWN
CONNECTED
FOUNDATION DRAWN

CONNECTED
FOUNDATION DRAWN

SANITARY SEWER

CRACKED OR
BROKEN PIPE

DETROMOTED

LATERAL
DISTRICT

CRACKED OR
BROKEN PIPE

DETROMOTED

LATERAL
DISTRICT

STORM SEWER
CROSS-CONNECTION
ON TO LATERAL
CONNECTION
DISTRICT
DISTRIC

Status Active

#### Description

To support on-going street projects and associated storm water line upgrades, this project is to provide closed-circuit television (CCTV) inspection to the citywide storm water pipe lines. The inspection results will be used by City staff and design engineer for City's storm water pipe line upgrade and maintenance.

#### Justification

Inspections are essential to maintain the system and reduce the potential for line breaks.

Expenditures	<b>Prior Years</b>	2023	2024	2025	Total
Construction/Rehab		800,000	800,000	800,000	2,400,000
Design		100,000	100,000	100,000	400,000
Eng, Admin Reimbursements		100,000	100,000	100,000	314,531
То	tal	1,000,000	1,000,000	1,000,000	3,114,531
Funding Sources	Prior Years	2023	2024	2025	Total
Revenue Bonds		1,000,000	1,000,000	1,000,000	3,114,531
Total		1,000,000	1,000,000	1,000,000	3,114,531

### **Budget Impact/Other**

Fully funding rehab/construction of storm water infrastructure can reduce operational cost by reducing "emergency" responses and more costly maintenance actions during lifecycle of infrastructure.