Date: 07-23-2025 12:58:31



## **Merged Document Report**

**Application No.: PL8824** 

Description :	
Address :	
Record Type :	PLAT

#### **Submission Documents:**

Document Filename
07.14.25 - Final Plat.pdf

#### **Comment Author Contact Information:**

Author Name	Author Email	Author Phone No.:
Mark Zans	markz2@cctexas.com	361-826-3553
Alex Harmon	alexh2@cctexas.com	361-826-1102


#### **General Comments**

Comment ID	Author : Department	Status	Review Comments	Applicant Response Comments
6	Alex Harmon : DS	Open	Update 7/23: CCW found that the existing (undersized) water line was abandoned as part of the TxDOT project meaning the lot is not served with any water making PIs required prior to plat approval.  Improvements Required for Recordation, per UDC 8.1.4. A. Streets: No Sidewalks: Yes, at site development B. Water: At site development depending on fireflow testing Fire hydrants: At site development C. Wastewater: Yes, unless using septic system as it appears D. Stormwater: No	

Comment Author : Department Status		or : Department Status Review Comments A		Applicant Response Comments
			E. Public open space: No F. Permanent monument markers: No	
			Please note, improvements required should be constructed to city standards, found in Article 8 and the IDM.	

### Corrections in the following table need to be applied before a permit can be issued

 Comment D	Page Reference	Annotation Type	Author : Department	Status	Review Comments	Applicant Response Comments
3	P001	Callout	Mark Zans : LD	Open	Change public health engineer to Manuel Garcia	



9.) DRAINAGE IMPROVEMENTS MUST ACCOMMODATE RUNOFF FROM THE UPSTREAM DRAINAGE AREA IN ITS ANTICIPATED MAXIMUM "BUILD—OUT" OR "FULLY DEVELOPED" CONDITION AND SHOULD BE DESIGNED TO PREVENT OVERLOADING THE CAPACITY OF THE DOWNSTEE AND DRAINAGE SYSTEM.

10.) IF THE OWNER RESPONSIBLE FOR MAINTAINING THE PERMANENT STORMWATER OR WATER QUALITY CONTROL FAILS TO MAINTAIN IT TO TXDOT ROW STANDARDS, THE OWNER MUST RECTIFY THE ISSUE.

11.) ANY DEVELOPMENT THAT ANTICIPATES AN INCREASE IN EXISTING TRAFFIC GENERATION MAY BE REQUIRED TO CONDUCT A TRAFFIC STUDY. THE NECESSARY IMPROVEMENTS IDENTIFIED IN THE TRAFFIC STUDY MAY NEED TO BE CONSTRUCTED BY THE DEVELOPER, BASED ON TXDOTS DISCRETION AND APPROVAL, PRIOR TO THE ACCESS CONNECTION BEING ESTABLISHED.

HUT ENTERPRISES, LLC,

HOUSTON, TEXAS 77036

9894 BISSONNET, SUITE 650

A TEXAS LIMITED LIABILITY COMPANY

INDICATES IRON ROD FOUND

INDICATES UTILITY EASEMENT

INDICATES EASEMENT

BUILDING LINE

PLAT BOUNDARY

INDICATES STORM DRAIN

INDICATES SQUARE FEET

INDICATES POINT OF BEGINNING

8. "P.O.B."

"ESMNT." 10. "STDR"

11. "S.F."

12. "U.E."

4.) SET 5/8 INCH STEEL RE-BAR SET WITH YELLOW PLASTIC CAP LABELED "BRISTER

OSMONUMENTED ON THE GROUND AND SHOWN AS NORTH 89'53'44" WEST, ON SURVEY MADE BY H.M. WARREN, A REGISTERED PROFESSIONAL LOND SURVEYOR, LICENSE NO. 1465, DATED AUGUST 30, 2002.

6.) BY GRAPHIC PLOTTING ONLY, THIS PROPERTY IS IN ZONES X ON FLOOD INSURANCE RATE MAP, COMMUNITY PANEL NO. 4855C 0505 G, CITY OF CORPUS CHRISTI, TEXAS, WHICH BEARS AN EFFECTIVE DATE OF OCTOBER 13, 2022 AND IS NOT IN A SPECIAL FLOOD HAZARD AREA.

5.) BEARINGS ARE BASED ON THE CENTERLINE OF FARM TO MARKET ROAD 43.


SURVEYING" AT ALL LOT CORNERS, EXCEPT WHERE NOTED.

LOTS: 1 BLOCKS: 1 REASON FOR FINAL PLAT: TO CREATE ONE (1) LOT

JULY, 2025

**SURVEYOR:** BRISTER SURVEYING 5506 CAIN DRIVE, CORPUS CHRISTI, TEXAS 78411 PHONE: 361-850-1800 FAX: 361-850-1802 FIRM #10072800

bristersurveying@corpus.twcbc.com



# **INTERFIELD GROUP** engineering Larchitecture 401 STUDEWOOD, SUITE 300 TEL. (713) 780-0909

(INTERFIELD PROJ. #: 24035.00)

HOUSTON, TEXAS 77007 TX. REG. NO. F-5611

WWW.INTERFIELD.NET