

City of Corpus Christi

Senior Buyer – Cynthia Perez

PRICE SHEET

Bayfront Fountain Repairs

Fountain Repairs, LLC  
Pearland, Texas

ITEM	DESCRIPTION	QTY	UNIT	UNIT PRICE	PRICE TOTAL
1	<b>Repair- Tech Labor</b> Repair- Technician labor rate for maintenance/repair to fountain	1	EA	\$6,590.00	\$6,590.00
2	<b>Repair- Help Labor</b> Repair- Helper labor rate for maintenance/repair to fountain	2	EA	\$4,567.00	\$9,134.00
3	<b>Evoqua Delta</b> Evoqua UV ELP 610 stainless steel construction UV Filtration	1	EA	\$20,000.00	\$20,000.00
4	<b>MNT20/30 POOLGRADE 50LB Sand (20-30)</b> 200lbs	91	EA	\$9.28	\$844.48
5	<b>A91 0.75THP 1S 115 3'STCORD</b> 3/4 hp speck pumps	2	EA	\$840.00	\$1,680.00
6	<b>6 inch pipe and fittings</b> Various PVC fittings and pipe lengths to install new UV and new filter pump	1	EA	\$950.00	\$950.00
7	<b>10 hp filter pump</b> Replacement filter pump Speck Normblock 10hp all plastic construction with new basket strainer, hair & lent, 230/480v 3 phase	1	EA	\$12,156.32	\$12,156.32
8	<b>Chemical Controller</b> Chemical Controller	1	EA	\$7,450.45	\$7,450.45
9	<b>CueServer 950</b> Cue Server 950 with onboard web server and custom screens to control fountain	1	EA	\$2,954.00	\$2,954.00
	<b>TOTAL</b>				\$61,759.25