TECHNICAL REVIEW COMMITTEE (TRC) PLAT REVIEW COMMENTS

Staff Only: TRC Meeting Date: TRC Comments Sent Date: 4/11/19 Revisions Received Date (R1): 5/1/19 Staff Response Date (R1): 5/20/19 Revisions Received Date (R2): 6/4/19 Staff Response Date (R2): 6/21/19 TRC Engineering comment #1 response updated 7/25/19 Revisions Received Date (R3): 8-14-19 Staff Response Date (R3): 8-14-19 Planning Commission Date: 8/21/19

Interdepartmental Staff and outside agencies have reviewed and prepared comments for the proposed plat. All plats must comply with applicable review criteria. These comments are intended to be final. All corrected plats must be submitted with a comment resolution (response) letter for staff review.

Major plats, in compliance with review criteria, are recommended for approval to the Planning Commission by the TRC. Development Services staff will determine when the plat is scheduled for Planning Commission. Administrative plats, in compliance with review criteria, are approved by the Director on a rolling basis.

Project: <u>19PL1035</u>

MARTIN PLAZA, BLOCK 1, LOTS 1A & 1B (REPLAT – 2.77 ACRES)

Located west of CR 69 (Hazel Bazemore) and south of FM 624 (Northwest Boulevard).

Zoning: CG-2

Owner: Spoil Island, LLC Engineer: LJA Engineering, Inc.

The applicant proposes to plat the property to divide a single lot into two lots.

GIS							
			Applicant Response				
No.	Sheet	Comment	5/1/19	Staff Resolution	Applicant Response	Staff Resolution	
		Lot 1A is a duplicate lot number and not					
1	Plat	allowed. Choose another lot number.	Lot 1A is changed to Lot 1C	Correct			
		The plat closes within acceptable engineering					
2	Plat	standards.	Agree	Correct			
		Plat notes # 1 shall include the actual					
3	Plat	projection/basis of bearing.	Change noted on plat	Correct			

LAND	DEVEL	OPMENT				
			Applicant Response			
No.	Sheet	Comment	5/1/19	Staff Resolution	Applicant Response	Staff Resolution
		Add Riverwood Drive as a reference on the			Addition of Riverwood Dr label on	
1	Plat	Location Map.	Corrected as requested	Not Addressed.	Vicinity Map.	Addressed.
		Change Lot 1A to Lot 1C. Correct all				
		references to lot numbers on the plat,				
		including lot number on plat note # 9, Owner's				
2	Plat	certificate, and title.	Corrected as requested	Addressed.		
		Place the Block number before the Lot number				
3	Plat	on the Plat title.	Corrected as requested	Addressed.		
		Label dashed line area presumed to be access				
		easement / driveway. Provide document	Original document			
4	Plat	reference if existing.	provided	Addressed.		

5 Plat	Add access easement covering drive aisles/parking lots as depicted in Utility Plan, not included in Document No. 2002025429.	All lots are currently served by the existing Ingress-Egress Easement as shown. Owner would prefer a cross access agreement as noted on plat revision note 9	Not Addressed entirely. Recommend adding an access easement shown with dashed lines connecting from the existing (Doc # 2002025429) to the east adjacent property (Taylor Best) to meet TXDoT's cross access easement requirement for all lots. Plat note 9 Access easement per plat will satisfy the driveways not part of TXDoTs requirement (frontage).	Access easement lines extended and called out with leader and description. (Access easement to satisfy TXDOT cross access requirement dedicated with their plat).	Not addressed. Add Lot 2B to Plat Note 9. Lot 2B was added to Plat Note 9. Addressed.
6 Plat	Draw and label the Y.R.	There are no yard requirements	Not Addressed. As a standard for lot frontages, the YR's and UE's are a requirement. 20' YR and 15' UE along the front property line.	Addition of 20' YR and 15' UE lines added with leader and respected callouts.	Addressed.
7 Plat	Need private U.E. on Lot 1A to accommodate sewage from Lot 1C, going to private lift station. Also for force main along boundary.	Corrected as requested	Addressed.		
71100	Note 7: change "Yard Requirements" to "Yard	corrected as requested	Addressed.		
8 Plat	Requirement".	Corrected as requested	Addressed.		
	Note 9: change to read: "SHARED ACCESS				
9 Plat	ACROSS LOTS 1B, 1C & 3A"	Corrected as requested	Addressed.		
10 Plat	Note 10: remove. The retention pond does not appear to be on this property.	Corrected as requested	Addressed.		
11 Plat	Note 11: at the end, add: " is required."	Corrected as requested	Addressed.		
	Correct the Plat Description under the Plat				
12 Plat		Corrected as requested	Addressed.		
	Move 50' UE label and dimension leader				
13 Plat	within platted area.	Corrected as requested	Addressed.		
44.01-7	Replace all references to "amending" with	Compared and an annual of	A data and		
14 Plat	"replat".	Corrected as requested	Addressed.		
15 Plat	Label the complete legal description of the western and eastern adjacent parcels.	Corrected as requested	Not Addressed. East property is Vol. 68 Pg 591. For west property, provide full legal description and Volume and page.	Our citation for Taylor Best Plaza East property is correct @ Vol. 68, Pg. 669. Citation for West Property is correct at Vol. 68, Pg. 591.	Addressed.

PLANNING/E	LANNING/Environment & Strategic Initiatives (ESI)							
No. Sheet	Comment	Applicant Response	ponse Staff Resolution Applica	Applicant Response Staff Resolution				
1 Plat	No comment.							

DEVELOPMENT SERVICES ENGINEERING	DEVELOPMENT SERVICES ENGINEERING			
Action	Yes	No		
Public Improvements Required?	Yes			
Water		No		
Wastewater		No		
Stormwater		No		
Fire Hydrants		No		
Manhole		No		
Sidewalks	Yes			
Streets		No		

Refer to UDC Section 3.8.3.D Waivers if applicable.

Applicant Response on Waiver:		
DEVELOPMENT SERVICES ENGINEERING		

K:\DevelopmentSvcs\SHARED\Legistar\2019 PC Agenda Items\09.18.19\Plats\Martin Plaza\Martin Plaza Blk 1 Lot 1A1B-Resolution Comments.R3.xlsx

			Applicant Response			
No.	Sheet	Comment	5/1/19	Staff Resolution	Applicant Response	Staff Resolution
				Not Addressed: Indicate limits of shared access in	Addressed and explained in	Not addressed. Add Lot 2B to Plat Note 9.
		Provide and label shared access agreement	Same as land development	conformance with Utility Plan layout. (Taylor Best,	comment No. 5 of the Land	Lot 2B was added to Plat Note 9.
1	Plat	between proposed lots.	notes	Lot 1B)	Development table.	Addressed.
2	Plat	Provide storm water/drainage agreement between proposed lots and adjacent Lot 3A.	Corrected as requested	Not Addressed: Provide outfall conveyance agreement to abutting property (Lot 3A).	Existing drainage plan as shown on As-Builts has been in place for years. Obviously designed and agreed to by all parties. No drainage agreement document exists.	Provide a new drainage agreement document. Drainage agreement document provided. Addressed.
3		Provide and label the Private Utility Easement for existing wastewater service line crossing lot line.	Corrected as requested	Addressed on Plat Instrument.		Addressed
4		Provide and label a 15 feet Utility Easement for existing 3" wastewater force main line, running north of lift station. Confirm whether private or public.	An easement for this line is already recorded as noted on plat revision	Addressed.		Addressed
5	Utility Plan	Provide location of existing fire hydrants (it may required additional public improvements).	As shown on previously submitted utility plan	Not Addressed: Provide location of FHA's on 12- inch water within FM 624 ROW.	Addition of dimensions with breaklines and fire hydrant symbol to show location within FM 624 ROW.	The updated Utility Plan wasn't included with revisions. The Utility Plan was updated to include revisions. Addressed.
6		Provide calculation of existing private wastewater lift station and city main receiver line has capacity to handle the new proposed lot.	See lift station calculation sheet performed by RVE 8- 2005 (attached)	Addressed.		Addressed
7		Public Improvements are required for sidewalk and may be required for fire hydrants. Public Improvements shall be completed and accepted prior of plat recordation.	There are no public sidewalks on this or any surrounding properties. See note 5 above for fire hydrants	Not Addressed. Sidewalk construction required	No longer required as per Bill Green and email from Jalal Saleh, PE on May 23, 2019. "Since no sidewalks exists along the south side of NW Blvd if you submit a waiver request for the sidewalk, Land Development Division will support the request If a request is made for a sidewalk waiver, DSE supports this request."	Submit the Sidewalk waiver application as per UDC Section 3.8.3.D and the \$160.00 Waiver application fee. Sidewalk waiver application provided. Waiver received.

UTI	TILITIES ENGINEERING (WATER AND WASTEWATER)							
			Applicant Response					
No.	Sheet	Comment	5/1/19	Staff Resolution	Applicant Response	Staff Resolution		
					Contact was made and NCWID			
		Please contact Nueces County Water Control			provided a letter resolving this			
	Utility	& Improvement District #3 for comments on		Provide a copy of approved NCWID #3 plans will	matter. Letter will be attached to			
1	l Plan	water.	Water is available	be required.	email.	Addressed.		
				Addressed: Public wastewater service not				
	Utility	Wastewater construction is required for		required as service provided through on site				
2	2 Plan	platting.	None required	private infrastructure.				
		All public wastewater mains shall be in a						
		minimum of a 15' utility easement (verify						
	Utility	whether lift station and mains on the property		Addressed: Private wastewater infrastructure				
3	Plan	are public or private).	As noted on plat	easement addressed by DSE 4 comment above.				

٦	IRAFFIC ENGINEERING						
		Applicant Response					
ſ	No. Sheet	Comment	5/1/19	Staff Resolution	Applicant Response	Staff Resolution	

	Proposed driveway access to Northwest			
	Boulevard (FM 624) shall conform to TXDOT			
1 Plat	access management standards.	It does	Addressed.	

FLO	OODPLAIN						
No.	Sheet	Comment	Applicant Response	Staff Resolution	Applicant Response	Staff Resolution	
	1	No comment.		Addressed.			

FIRE	RE DEPARTMENT - INFORMATIONAL, REQUIRED PRIOR TO BUILDING PERMIT					
			Applicant Response			
No.	Sheet	Comment	5/1/19	Staff Resolution	Applicant Response	Staff Resolution
		WATER DISTRIBUTION SYSTEM STANDARDS				
		Fire Hydrant flow				
		Mercantile/Commercial Areas:				
		Light Mercantile areas shall 1,500 GPM with				
		20 psi residual				
		Fire hydrant every 300 feet and operational.				
1	Plat	,,	In place	Informational.		
_		Note: Appendix B IFC 2015 Table B105.2 (Due				
		to low water pressure in this area)-if the				
		building has a sprinkler system installed, the				
		water supply is allowed to be reduced to 1,000				
		GPM	Noted	Informational.		
		FIRE APPARATUS ACCESS ROADS				
		SECTION D102				
		REQUIRED ACCESS	In place	Informational.		
		REQUIRED ACCESS	in place			
		D102.1 Access and loading. Facilities, buildings				
		or portions of buildings hereafter constructed				
		shall be accessible to fire department				
		apparatus by way of an approved fire				
		apparatus access road with an asphalt,				
		concrete or other approved driving surface				
		capable of supporting the imposed load of fire				
		apparatus weighing at least 75,000 pounds (34				
		050 kg).	In place	Informational.		
		Note: Fire Access roads to neighboring				
		structures shall be blocked, gated, or				
		barricaded.				
		Note: a drivable surface capable of handling				
		the weight of fire apparatus is require to be in				
		place prior to "going vertical" with the				
		structure.	In place	Informational.		
	1	SECTION D103				
		D103.1 Access road width with a hydrant.				
		Where a fire hydrant is located on a fire				
		apparatus access road, the minimum road				
		width shall be 26 feet (7925 mm), exclusive of				
		shoulders	In place	Informational.		
		D103.6 Signs. Where required by the fire code				
		official, fire apparatus access roads shall be				
		marked with permanent NO PARKING—FIRE				
		LANE signs	In place	Informational.		
	1		p	in or mational.		

D103.6. Signs shall have a minimum dimension of 12 inches wide by 18 inches high and have red letters on a white reflective background. Signs shall be posted on one or both sides of the fire apparatus road as required by Section D103.6.1 or D103.6.2.	In place	Informational.	
D103.6.1 Roads 20 to 26 feet in width. Fire lane signs as specified in Section D103.6 shall be posted on both sides of fire apparatus access roads that are 20 to 26 feet wide.	In place	Informational.	
D103.6.2 Roads more than 26 feet in width. Fire lane signs as specified in Section D103.6 shall be posted on one side of fire apparatus access roads more than 26 feet wide and less than 32 feet wide.	In place	Informational.	
D104.3 Remoteness. Where two fire apparatus access roads are required, they shall be placed a distance apart equal to not less than one half of the length of the maximum overall diagonal dimension of the lot or area to be served,			
measured in a straight line between accesses.	In place	Informational.	

GAS	GAS	
-----	-----	--

-

No. Sheet	Comment	Applicant Response	Staff Resolution	Applicant Response	Staff Resolution	
1 Plat	No comment.		Addressed.			

PA	PARKS							
No	Sheet	Comment	Applicant Response	Staff Resolution	Applicant Response	Staff Resolution		
	1 Plat	No comment. Plat has standard comment.		Addressed.				

			Applicant Response			
No.	Sheet	Comment	5/1/19	Staff Resolution	Applicant Response	Staff Resolution
		This replat is not located along an existing or				
1	Plat	foreseeably planned CCRTA service route.	Noted	Addressed.		

NAS-CORPUS CHRISTI						
No. Sh	heet	Comment	Applicant Response	Staff Resolution	Applicant Response	Staff Resolution
1 PI	Plat	No comment.		Addressed.		

COR	CORPUS CHRISTI INTERNATIONAL AIRPORT						
No.	Sheet	Comment	Applicant Response	Staff Resolution	Applicant Response	Staff Resolution	
1	Plat	No comment.		Addressed.			

	AEP-TRANSMISSION						
No. Sheet C	Comment	Applicant Response	Staff Resolution	Applicant Response	Staff Resolution		
1 Plat N	No comment.		Addressed.				

AEP-DISTRIBUTION						
No. Sheet	Comment	Applicant Response	Staff Resolution	Applicant Response	Staff Resolution	
1 Plat	No comment.		Addressed.			

TXDOT					
		Applicant Response			
No. Sheet	Comment	5/1/19	Staff Resolution	Applicant Response	Staff Resolution
	Provide cross access easement on Plat and on				
	Deeds / shared use entrance agreement for			Addressed and explained in	
	both lots. Cross Access Easement to connect		Not Addressed. Adjacent development is (Taylor	comment No. 5 of the Land	
1	to adjacent development on the east side.	As shown on plat	Best, Lot 1B)	Development table.	Addressed.
	Note on Plat " No additional access from	This verbiage has been		Addressed and explained on Final	
		added to note 12 on plat	Not Addressed.	Plat under Notes No. 12	Addressed.
	No drainage to FM 624 right of way. If				
	developer wishes to drain into TxDOT drainage				
3	system, approval is required.	See revised note 10 on pla	t Addressed.		

NU	NUECES ELECTRIC							
No.	Sheet	Comment	Applicant Response	Staff Resolution	Applicant Response	Staff Resolution		
	L Plat	No comment.		Addressed.				

INFORMATIONAL

Comments noted below apply to the preliminary site/utility/transportation plan and preliminary storm water quality management plan (SWQMP) as observations

for information only.

These comments should be considered during subsequent site and public infrastructure development but may be required as a condition for plat consideration by the Planning Commission for approval.

Additional comments may be issued with the subsequent submittal plans associated with the property development.

LAND DEVELOPMENT

1. Prior to recordation, provide a tax certificate indicating that all taxes have a \$0.00 balance, along with the submittal of the original tracing.