

Substandard case started 4/11/2023

Structure(s) deemed substandard based on the following findings:

- Structure(s) do not meet the minimum requirements and standards as set forth in the Corpus Christi Property Maintenance Code.
- Exterior of the structure(s) are not in good repair, is not structurally sound, and does not prevent the elements or rodents from entering the structure.
- Interior of the structure(s) are not in good repair, is not structurally sound, and is not in a sanitary condition.
- Structure(s) are unfit for human occupancy and found to be dangerous to the life, health, and safety of the public.

City Recommendation: Demolition of the residential & accessory structures (Building Survey attached)

Property located in a residential area.

According to NCAD, the owner took possession of property 9/28/2001.

#### Case, Abatement, and Citation History

Total number of Code complaints: 1

Total number of cases: 8

Owner Compliance: 2

City Abatements: 6

Citations issued: 1



Date	Case Type	Violation(s)	Status
06/07/2024	Vacant Building	Tall weeds, litter and solid	In progress
		waste & sidewalks, curbs and	
		gutters	
04/18/2024	Junk Vehicle	Inoperable vehicle on property	Seized by City
04/17/2024	Unsecure Vacant	Unsecure openings	Abated by City
	Building	No.	
04/15/2024	Substandard	Substandard main &	In progress
	Structure	accessory structure	
06/09/2023	Vacant Building	Tall weeds, litter and solid	Abated By City-
		waste & sidewalks, curbs and	Expired
		gutters	
12/11/2018	PMC Standards	Openable Windows & Roofs	Expired
		and Drainage	
11/21/2018	Care of Premises	Tall weeds, Dangerous Fence	Expired
09/13/2018	Care of Premises	Litter and solid waste,	Expired
		sidewalks, curbs & gutters	
	=== = =	clean	

### Abatement history for 938 MENDOZA ST.

	<u>Date</u>	Cost/Admin Fee	Case Type
1.	07/25/2024	\$200.19/\$412	Abatement of tall weeds
2.	10/25/2024	\$320/\$412	Abatement of tall weeds
3.	05/24/2024	\$460 /\$412	Abatement of unsecure openings
4.	02/08/2024	\$206.39/\$412	Abatement of tall weeds
5.	04/19/2024	\$243.41/\$412	Abatement of tall weeds
6.	05/23/2024	\$245.19/\$412	Abatement of tall weeds

Total: \$4147.18



# CCPD calls to property:

Nature of Call	938 Mendoza St.
Unknown Nature Non Inury	1
Destruction or Criminal Mischief In Progress	1
Fireworks Possession or Use In Progress Contact Requested	1
Law Enforcement Investigation Field Event	7
Broadcast Info Law Enforcement Only	1
Disturbance in Progress	10
Disturbance injuries Involved	1
Disturbance weapons Involved	2
Shots Fired/Deadly Conduct Shots Heard in Area	1
Suspicious or Unusual Suspicious Person or Persons	1
Theft of Property or Services Just Occurred	1
Disturbance not Progress	11
Law Enforcement Investigation Explain Type	1
Property or Item Found Explain Type	1
Assault in Progress	1
Assault weapons Involved	1
Burglary in Progress	1
LE Assist with Child Custody	6
Traffic or Public Hazard Reckless or Speeding Driver	1
Back Up Routine For EMS Unit	1
Quality of Life Code Enforcement Assist	1
	53

## Attempted contact with Property Owner(s)

DATE	NAME	CONTACT DETAILS
11/18/2024	Rosemary Cantu-Heir to	Stated the property was to be handled by the
	property	oldest daughter Maria C. Chavez. She provided
		more information regarding her siblings who are
		deceased.
11/21/2024	Roy Cantu-Heir to property	Appeared at November hearing and was
		informed the property had been pulled from the
		agenda. He was informed the process of the



		BSB proceedings and had a bit in interest in
		taking ownership of the property.
1/7/2025	Clemente (Arturo) Cantu-	Left message with departments stating he wants
	Heir to property	nothing to do with the property.

•	L/2/2(	J25
(	Code	Compliance Supervisor: Roland Maldonado
(	Case#	V229763-041524
F	rope	rty Owner: Estate of Maria H. Cantu c/o Maria C. Chavez IND EXEC
<u> </u>	Addre	ss (⊠Residential ☐Commercial): 938 Mendoza St.
S	Staff R	Recommendation(s): Demolition
[	□Resi	idential Structure only   Residential and Accessory Structure
	Com	nmercial Structure only   Commercial and Accessory Structure
C	lue to	the provisions of Section 13-22 (H)(1)(c) of the Corpus Christi Property Maintenance Code and substandard and dilapidated condition of the structure(s), a hazard to the health, safety, and e of the public is henceforth declared.
		ore, the owner be required to <b>demolish</b> the structure(s) within thirty (30) days. If demolition is arted and completed as required, then the City be authorized to demolish.
<u>N</u>	lotice	<u>.</u> <u>S</u>
	1. 2. 3. 4.	Letters of substandard conditions sent by certified mail. Final notice sent by certified mail. Certified letter of hearing sent by certified mail Notice of hearing published in newspaper.
Α	dditic	onal
	1. 2. 3. 4. 5.	Owner Deceased:  No  Yes If deceased verification by:  Obituary  Structure Entered by:  Search Warrant  Consent Given by:  Taxes due:  Current  Past due -Amount owed: \$26,664.83  Utilities:  Active  Inactive-Last active date: 4/13/2023  Year Structure Built: 1971
	6.	Lawsuits: ⊠Yes □No

 $\square$ No

6. Lawsuits: ⊠Yes □No7. Code Enforcement Maintaining Property: ⊠Yes

#### **COMPLAINT**

Thursday, January 2<sup>nd</sup>, 2025

Building Standards Board City of Corpus Christi 2406 Leopard St. Corpus Christi, Texas 78408

RE: 938 Mendoza St.

Case # V229763-041524

OWNER: Est. of Maria H. Cantu

Code Compliance Supervisor Roland Maldonado

#### Dear Board Members:

Pursuant to Article II and in accordance with Section 13-22(B), of the Corpus Christi Property Maintenance Code, this Department has initiated and prepared the above listed case for your review and consideration. On May 22, 2024, the code official determined that there were reasonable grounds to believe there was a violation(s) of the Corpus Christi Property Maintenance Code or any rule or regulation concerning the health, safety, or general welfare adopted by the city as it relates to structures or premises and gave notice of such alleged violation to the owner of the property. Thirty days have elapsed since the notice of violation(s) was provided and such violation(s) have not been cured.

Staff recommends a hearing be set for not less than ten (10) days or more than forty-five (45) days from the date of this complaint. At this hearing staff recommendation for the above listed property will be repair/demolition.

If you have any questions concerning the above, please call (361) 826-3046.

Roland Maldonado

Supervisor

Development Services Code Compliance Division

cc: Carlos Martinez, Monica Pareso, Catherine Giffin, John Solberg, Merced Pena, William Ewing, Chic Henderson

CASE TIMELINE FOR 938 MENDOZA ST.			
Activity	Date	Legal Requirement	Legal Reference
Code Enforcement Notified of Potential Violation	4/11/2024	n/a	n/a
Initial Inspection Completed	4/11/2024	When building, structure or premise thought to be substandard	Corpus Christi Property Maintenance Code 104.2
Notice of Violation Mailed to Last Known Addresses	5/30/2024	When there are reasonable grounds to believe there is a violation	City Ordinance Sec. 13-22(A) & (D)(2)
Notice of Violation Posted in Newspaper	7/19/2024 & 7/22/2024	When owner is unknown, whereabouts unknown, or where service of notice has failed (Published twice w/in a 10 day period)	City Ordinance Sec.13- 22(A) & (D)(3)
Deadline to comply with Newspaper Notice of Violation	8/19/2024	When 30 days have elapsed from the date of first publication	City Ordinance Sec. 13-22(B)
Notice Received	6/11/2024	Returned mail rec'd 6/11/24-Return to sender, refused, unable to forward	n/a
Returned Notice of Violation Posted at Front Door of Property	9/23/24 -9/27/24 & 9/30/24-10/4/24	When notice is returned showing unclaimed or not delivered	City Ordinance Sec. 13-22(A) & (D)(4)
Deadline to comply with Mailed Notice of Violation	6/30/2024	30 days from receipt of the notice	City Ordinance Sec. 13-22(A)(5)
Re-inspection	7/22/2024	Not less thans 30 days from receipt of the notice or when 30 days have elapsed from date of first publication	City Ordinance Sec. 13-22(B)
Complaint filed with BSB	1/2/2025	When owner refused to comply; when not cured within 30 days from receipt of notice or any further agreed time; or when 30 days have elapsed from date of first publication	City Ordinance Sec. 13-22(B)(2)
Notice of Hearing Mailed to Last Known Address	1/3/2025	At least 10 days prior to hearing	City Ordinance Sec. 13-22(C) & (D)(2)
Notice of Hearing Posted in Newspaper	12/30/2024 & 12/31/2024	At least 10 days prior to hearing when owner is unknown, whereabouts unknown, or where service of notice has failed (Published twice w/in a 10 day period)	City Ordinance Sec.13- 22(C) & (D)(3)
Notice of Hearing Filed with County Clerk	1/2/2025	At least 10 days prior to hearing	City Ordinance Sec. 13- 22(C) & Tx Local Gov't Code 214.001€
Returned Notice of Hearing Posted at	1/13/25-1/17/25 &	When notice is returned showing	City Ordinance
Front Door of Property	1/20/25-1/22/25	unclaimed or not delivered	Sec. 13-22(C) & (D)(4)
BSB Agenda Posted	1/17/2025	72 hours (3 days) before scheduled time of hearing	Texas Govt. Code 551.043(a)
BSB Hearing	1/23/2025	Not less than 10 days nor more than 45 days after Complaint filed	City Ordinance Sec. 13-22 (C)



# 938 MENDOZA ST

Aerial View























































# City of Corpus Christi – BUILDING SURVEY

Inspection Date: 4/11/2024		
Zoning Use: RS-6		
Revised Date: 05/24/2024		
Officer: Diana T. Garza		
Property Address: 938 MENDOZA ST		
Legal Description: LAGUNA ACRES I	LT 21B BK 5	
Owner: CANTU MARIA H ESTATE O	F	
Mail to: C/O MARIA C CHAVEZ IND E	EXEC 6315 VICTORIA	
City, State, Zip: HOUSTON, TX 77020	0	
X         Dwelling         Comr           X         Wood Frame         Maso           X         Vacant         Occur           Placard Posted on: 5/22/2024		Sq. Ft. 1Story# of Units XInside InspectionPlacard
Plumbing, Electrical, Mechanical, F. Permits Required:	ire, Health and Zoning.	
BuildingPlumb FireHealtl		Mechanical
FireHealti		Mechanical
	h Other:	MechanicalAdditional Alarms Required
FireHealth Smoke Alarms:MissingInope OUTSIDE WALL: (304.1, 304.2 304.4 & 304.6) Type:Charred Wood	hOther:  rativeImproperly Located  ROOF: (304.1 & 304.7)  Type:Charred Wood	Additional Alarms Required  FOUNDATION: (304.1, 304.4 & 304.5)  Type:Inadequate Support
Fire Health  Smoke Alarms: MissingInope  OUTSIDE WALL: (304.1, 304.2 304.4 & 304.6) Type:Charred Wood XRotten Wood XRotten Corner Boards	hOther:  rativeImproperly Located  ROOF: (304.1 & 304.7) Type:	Additional Alarms Required  FOUNDATION: (304.1, 304.4 & 304.5) Type:
Fire Health  Smoke Alarms: MissingInope  OUTSIDE WALL: (304.1, 304.2 304.4 & 304.6) Type:Charred Wood XRotten Wood XRotten Corner BoardsMissing Boards	hOther:  ROOF: (304.1 & 304.7) Type:Charred Wood Rotten EavesRotten Rafter Tails Rotten Decking	Additional Alarms Required  FOUNDATION: (304.1, 304.4 & 304.5) Type:Inadequate SupportRotten WoodPiers LeanPiers Missing
Fire Health  Smoke Alarms: MissingInope  OUTSIDE WALL: (304.1, 304.2 304.4 & 304.6) Type:Charred Wood X	hOther:  ROOF: (304.1 & 304.7) Type: Charred Wood Rotten Eaves Rotten Rafter Tails Missing Shingles	Additional Alarms Required  FOUNDATION: (304.1, 304.4 & 304.5) Type:Inadequate SupportRotten WoodPiers LeanPiers MissingCracks/Perimeter Wall
Fire Health  Smoke Alarms: MissingInope  OUTSIDE WALL: (304.1, 304.2 304.4 & 304.6) Type:Charred Wood X	hOther:  ROOF: (304.1 & 304.7) Type: Charred Wood Rotten Eaves Rotten Rafter Tails Rotten Decking Missing Shingles XDeteriorated Shingles	Additional Alarms Required  FOUNDATION: (304.1, 304.4 & 304.5) Type:Inadequate SupportRotten WoodPiers LeanPiers MissingCracks/Perimeter WallCracks/Slab
Fire Health  Smoke Alarms: MissingInope  OUTSIDE WALL: (304.1, 304.2 304.4 & 304.6) Type:Charred Wood XRotten Wood XRotten Corner BoardsMissing Boards XBadly in Need of PaintSiding Broken / MissingHoles	hOther:  ROOF: (304.1 & 304.7) Type: Charred Wood Rotten Eaves Rotten Rafter Tails Rotten Decking Missing Shingles Leaks Leaks	Additional Alarms Required  FOUNDATION: (304.1, 304.4 & 304.5) Type:Inadequate SupportRotten WoodPiers LeanPiers MissingCracks/Perimeter WallCracks/SlabPads Missing/Cracked
Fire Health  Smoke Alarms:     Missing Inope  OUTSIDE WALL:     (304.1, 304.2 304.4 & 304.6)     Type:     Charred Wood X Rotten Wood X Rotten Corner Boards     Missing Boards X Badly in Need of Paint     Siding Broken / Missing     Holes     Cracks	ROOF: (304.1 & 304.7) Type: Charred Wood Rotten Eaves Rotten Rafter Tails Rotten Decking Missing Shingles X Deteriorated Shingles Leaks Sags	Additional Alarms Required  FOUNDATION: (304.1, 304.4 & 304.5) Type:Inadequate SupportRotten WoodPiers LeanPiers MissingCracks/Perimeter WallCracks/SlabPads Missing/CrackedMissing Skirting
Fire Health  Smoke Alarms: MissingInope  OUTSIDE WALL: (304.1, 304.2 304.4 & 304.6) Type:Charred Wood X	ROOF: (304.1 & 304.7) Type: Charred Wood Rotten Eaves Rotten Rafter Tails Rotten Decking Missing Shingles X Deteriorated Shingles Leaks Sags Buckled	Additional Alarms Required  FOUNDATION: (304.1, 304.4 & 304.5) Type:Inadequate SupportRotten WoodPiers LeanPiers MissingCracks/Perimeter WallCracks/SlabPads Missing/CrackedMissing SkirtingMissing Access Cover
Fire Health  Smoke Alarms: MissingInope  OUTSIDE WALL: (304.1, 304.2 304.4 & 304.6) Type:Charred Wood XRotten Wood XRotten Wood XRotten Corner BoardsMissing Boards XBadly in Need of PaintSiding Broken / MissingHolesCracksBuckledLeans	ROOF: (304.1 & 304.7) Type: Charred Wood Rotten Eaves Rotten Rafter Tails Rotten Decking Missing Shingles X Deteriorated Shingles Leaks Sags Buckled Collapsed	Additional Alarms Required  FOUNDATION: (304.1, 304.4 & 304.5) Type:Inadequate SupportRotten WoodPiers LeanPiers MissingCracks/Perimeter WallCracks/SlabPads Missing/CrackedMissing SkirtingMissing Access CoverExposed Sills
Fire Health  Smoke Alarms: MissingInope  OUTSIDE WALL: (304.1, 304.2 304.4 & 304.6) Type:Charred Wood X	ROOF: (304.1 & 304.7) Type: Charred Wood Rotten Eaves Rotten Rafter Tails Rotten Decking Missing Shingles X Deteriorated Shingles Leaks Sags Buckled Collapsed	Additional Alarms Required  FOUNDATION: (304.1, 304.4 & 304.5) Type:Inadequate Support Rotten Wood Piers Lean Piers Missing Cracks/Perimeter Wall Cracks/Slab Pads Missing/Cracked Missing Skirting Missing Access Cover Exposed Sills Rotten Sills
Fire Health  Smoke Alarms: MissingInope  OUTSIDE WALL: (304.1, 304.2 304.4 & 304.6) Type:Charred Wood X	ROOF: (304.1 & 304.7) Type: Charred Wood Rotten Eaves Rotten Rafter Tails Rotten Decking Missing Shingles X Deteriorated Shingles Leaks Sags Buckled Collapsed X Worn	Additional Alarms Required  FOUNDATION: (304.1, 304.4 & 304.5) Type:Inadequate SupportRotten WoodPiers LeanPiers MissingCracks/Perimeter WallCracks/SlabPads Missing/CrackedMissing SkirtingMissing Access CoverExposed Sills

	<b>WINDOWS:</b> (304.1, 304.2 304.13, 304.13.1, 304.13.2, 304.14 &	<b>PORCHES:</b> (304.1, 304.2, 304.7 304.12, 305.4, 305.5 & 307.1)	10, <b>DOORS:</b> (304.1, 304.2, 304.13, 304.14, 304.15, 304.16, 304.18,
	304.17)	•	305.6 & 702.1)
	Charred Wood	Charred Wood	Charred Wood
<u>X</u>	Broken Glass	Missing / Broken Boards	Missing
<u>X</u>	Missing Screens	Loose	XDamaged
	Torn Screens X	Rotten Wood	Poor Fit
	Missing / Broken Sash X	Inadequate Support	Damaged / Missing Screen(s)
	Do Not Open	Support Post Missing	Off Hinges
<u>X</u>	Rotten Sills	Support Post Loose	Blocked Exit
<u>X</u>	Rotten / Broken Frames	Faulty Weather Protection	XRotten
	Other:	Other:	Other:
	STEPS: (304.1, 304.2	PLUMBING: B	ATHTUB / SHOWER
	304.10, 304.12, 305.4 & 305.5)		502.2, 502.3, 504.1, 504.2, 504.3, 505.1.1,
	Charred Wood	& 505.3) Missing	
	Rotten Wood		/ Broken / Missing
	Missing Boards	No Anti-Siphon	<u> </u>
<u>X</u>	Inadequate Support	Missing Overflo	w Plate
	Missing Handrails	Missing Tap	
	Faulty Weather Protection	Missing Showe	r Head
	Other:	Not Vented	
		XDisconnected	
		Stopped Up	
		Damaged Show	ver Stall
		Other:	
	PLUMBING: WATER CLOSET	WATER HEATI	
	(404.4.3, 502.1, 502.2, 502.3, 502.4, 5 504.1, 504.2, 504.3, 505.1.1, 506.1 & 8		603.2, 603.3, 603.4 603.5 & 603.6)
	Missing	Gas	
-	No Anti-Siphon Ballcock	Electric	
	Stopped Up	Missing	
	Poorly Anchored	XDisconnected	
	Seeps Around Bowl	Temperature Pr	essure Release Valve Missing
	Water Supply Line Leaks	Temperature Pr	essure Release Valve Broken
	Flush Ell Leaks	Drain Line Miss	<del>-</del>
	Runs Constantly	Not Approved P	•
	Tank Broken / Cracked	Not Extended O	outside
	Bowl Broken / Cracked	Elbowed Down	
<u>X</u>	Disconnected	Vent Missing / L	
	Missing Flush Handle	No Double Wall	•
	Missing Flapper	Nonconforming	
	Urinal; No Back-Flow Preventive	Inadequate Con	
	No Elongated Bowl / Open-end Seat Other:	Thermostat Miss	
	Ouigi.	No Gas Cut Off	
		Missing Firebox	Door Not Approved Pipe
			ated in Bathroom
			ated in Batriroom ated in Bedroom
		Fire Damaged	atod in Bodioom
		Other:	

	<b>LAVATORY:</b> (404.4.3, 502.1, 502.2, 502.3 502.4, 504.1, 504.2, 504.3, 505.1.1,	GAS SYSTEM: (602.1, 602.2, 602.3, 602.5
	502.4, 504.1, 504.2, 504.3, 505.1.1, 506.1 & 506.2)	603.1, 603.2, 603.3, 603.4, 603.5 & 603.6)
	,	One Dreaming Took Daming I
***************************************	Missing	Gas Pressure Test Required
	No Anti-Siphon Faucets	Gas Leak
	Faucets Leak / Broken / Missing	Line Appears to Enter Building Below Grade Level
	P" Trap Leaks / Missing	Gas Supply Not Approved Pipe
	Defective Trap	Rubber Hose to Space Heaters
	Stopped Up	Non-Rigid Pipe Run Through Partition Wall
	Water Supply Line Leak	Other:
	Loose from Wall	
	Nonconforming Waste Line	
<u>X</u>	Disconnected	
	Other:	
	KITCHEN SINK: (305.1, 305.3, 502.1,	PLUMBING MISCELLANEOUS:
	505.1.1, 506.1 & 506.2)	(504.1, 504.2, 504.3, 505.3, 506.2 & 507.1)
	Defective Trap	Open Clean Out / Water Leak; Yard / Under House
	Faucets Loose / Broken	Vent Stack Missing / Broken
	Faucets Missing	Vent Stack Not Extended Through Roof
-	"P" Trap Rubber Hose	Rain Guard Damaged / Missing
	Trap Leaks / Missing	Exposed Exterior PVC Pipe
	Stopped Up	PVC Water Supply Lines
<u>X</u>	Disconnected	Washer No "P" Trap / Not Vented / Not Cut Offs
	Damaged Counter Top	Sewer Line Stopped Up
	Damaged Back Splash	Sewer Running Out on Ground
<u></u>	Other:	Other:
	ELECTRICAL SERVICE: (604.1, 604.2	INSIDE WALLS AND CEILINGS:
	604.3, 604.3.1, 604.3.1.1, 604.3.2, 604.3.2.1	(305.1, 305.2, 305.3 & 404.3)
	605.1, 605.2 & 605.3)	
	Service Panel Burned	Charred Wood
	Service Missing	Paint Deteriorated
	Service Appears Below Code	Cracks
	Two-Wire Service	Holes
	Inadequate	Torn Wallpaper
	Defective	Damaged Paneling
X	Disconnected	XSheetrock Broken / Missing / Holes, 506.1 & 506.2
	Service Not Grounded	XSheetrock Mildewed / Buckled
	Missing Breakers / Fuses	XCeiling Damaged / Missing
	Missing Interior / Exterior Panel Cover	Water Damaged / Smoke Damaged
	Exposed Wiring	Impervious Material Around Tub
	Nonconforming Wiring in Panel	Enclosure Damaged / Missing
	Drops Too Low	Walls Around Tub Not Water Resistant
	Other:	Inadequate Ceiling Height
		Other:

	SYSTEM:	INTERIOR FLOORS:
	(604.3.2. 604.3.2.1, 605.1, 605.2 & 605.3)	(305.1, 305.2, 305.3 & 305.4)
	Burned Wiring / Plugs / Switches	Charred Wood
	Burned Fixtures	Rotten Wood
	Less Than 1 Duplex Recept. /20 liner ft-	XMissing Boards
	Bedroom/Living Rm/Dining Rm/Den/Kitchen	Holes
	No Small Appliance Circuits Over Kitchen	Cracks
	Counter Space with GFCI	Not Level
	Only One Small Appliance Circuit Over Kitchen	Ruckled
	Counter Space with NO GFCI	Torn
	Kitchen Appliance Circuits – No GFCI	XDamaged
X	Plugs Missing / Loose / Broken	Other:
X	Switches Missing / Loose / Broken	Otilei.
X	Fixtures Missing / Loose / Broken	
<u>X</u>	Missing Switch Cover / Plug Covers	
^	Extension Cords in Place of Permanent Wiring	
	Extension Cords in Place of Permanent WillingBathroom Circuit NO GFCI	
	Conduit Broken / Loose / Missing	
	No Separate Circuit For	
	No Disconnect for Air Conditioner	
	Exterior Lights Missing; Front / Back / Side	
	Porch Lights Broken / Missing / Loose	
	Other:	
	MECHANICAL:	ACCESSORY SURVEY:
	(403.1, 403.2, 603.1 & 603.6)	(302.7, 304.1, 304.2, 304.4, 304.5, 304.6 & 305.2)
	Vented Wall Heater Damaged / Missing	TYPE:
	Floor Furnace Damaged / Missing	Roof Type:
	Nonconforming Gas Line to Space Heater	XRotten
	Wall Heater with No Vent in Bathroom	Loose
	Thermostat Damaged / Missing	Torn
	Gas-Fired Heating Appliance within 2' of	Holes
	Tub / Shower / Water Closet	Missing
	Condensing Unit Descript of Italianian	
	Condensing Unit Damaged / Missing	
	Condensing Unit Damaged / Missing No Vent Fan or Window in Bathroom	Walls Type:
		Walls Type: XRotten
	No Vent Fan or Window in Bathroom	
	No Vent Fan or Window in Bathroom Vent Fan Missing / Not Operable	XRotten
	No Vent Fan or Window in Bathroom Vent Fan Missing / Not Operable Heat with No Vent in Commercial Building	XRotten Leaning
	No Vent Fan or Window in Bathroom Vent Fan Missing / Not Operable Heat with No Vent in Commercial Building Fire Damage	XRotten Leaning Buckled
	No Vent Fan or Window in Bathroom Vent Fan Missing / Not Operable Heat with No Vent in Commercial Building Fire Damage	XRottenLeaningBuckledMissing
	No Vent Fan or Window in Bathroom Vent Fan Missing / Not Operable Heat with No Vent in Commercial Building Fire Damage Other:	XRottenLeaningBuckledMissing
	No Vent Fan or Window in BathroomVent Fan Missing / Not OperableHeat with No Vent in Commercial BuildingFire DamageOther:  UNSANITARY CONDITIONS:	XRottenLeaningBuckledMissingOther:
	No Vent Fan or Window in BathroomVent Fan Missing / Not OperableHeat with No Vent in Commercial BuildingFire DamageOther:  UNSANITARY CONDITIONS: (308.3, 309.1, 504.1 & 505.1.2)	XRottenLeaningBuckledMissingOther:Foundation Type:
	No Vent Fan or Window in BathroomVent Fan Missing / Not OperableHeat with No Vent in Commercial BuildingFire DamageOther:  UNSANITARY CONDITIONS: (308.3, 309.1, 504.1 & 505.1.2)No Hot and Cold Water Supply	XRottenLeaningBuckledMissingOther:Foundation Type:Sunken

#### VIOLATION(S): 938 MENDOZA ST.

- 108.1.3 Structure unfit for human occupancy. A structure is unfit for human occupancy whenever the code official finds that such structure is unsafe, unlawful or, because of the degree to which the structure is in disrepair or lacks maintenance, is insanitary, vermin or rat infested, contains filth and contamination, or lacks ventilation, illumination, sanitary or heating facilities or other essential equipment required by this code, or because the location of the structure constitutes a hazard to the occupants of the structure or to the public.
- 302.7 Accessory structures. All accessory structures, including detached garages, shall be maintained structurally sound and in good repair.
- 304.1 General. The exterior of a structure shall be maintained in good repair, structurally sound and sanitary so as not to pose a threat to the public health, safety or welfare.
- 304.12 Handrails and guards. Every handrail and guard shall be firmly fastened and capable of supporting normally imposed loads and shall be maintained in good condition.
- 304.13 Window, skylight and door frames. Every window, skylight, door and frame shall be kept in sound condition, good repair and weather tight.
- 304.15 Doors. Exterior doors, door assemblies, operator systems if provided, and hardware shall be maintained in good condition. Locks at all entrances to dwelling units and sleeping units shall tightly secure the door. Locks on means of egress doors shall be in accordance with Section 702.3.
- 304.6 Exterior walls. Exterior walls shall be free from holes, breaks, and loose or rotting materials; and maintained weatherproof and properly surface coated where required to prevent deterioration.
- 304.7 Roofs and drainage. The roof and flashing shall be sound, tight and not have defects that admit rain. Roof drainage shall be adequate to prevent dampness or deterioration in the walls or interior portion of the structure. Roof drains, gutters and downspouts shall be maintained in good repair and free from obstructions. Roof water shall not be discharged in a manner that creates a public nuisance.
- 305.6 Interior doors. Every interior door shall fit reasonably well within its frame and shall be capable of being opened and closed by being properly and securely attached to jambs, headers or tracks as intended by the manufacturer of the attachment hardware.
- 504.1 General. Plumbing fixtures shall be properly installed and maintained in working order, and shall be kept free from obstructions, leaks and defects and be capable of performing the function for which such plumbing fixtures are designed. Plumbing fixtures shall be maintained in a safe, sanitary and functional condition.
- 505.1 General. Every sink, lavatory, bathtub or shower, drinking fountain, toilet or other plumbing fixture shall be properly connected to either a public water system or to an approved private water system. Kitchen sinks, lavatories, laundry facilities, bathtubs and showers shall be supplied with hot or tempered and cold running water in accordance with the International Plumbing Code as adopted and amended by the City.
- Exceptions: Facilities constructed lawfully without hot water.
- 602.3 Heat supply. Every owner and operator of any building who rents, leases or lets one or more dwelling units or sleeping units on terms, either expressed or implied, to furnish heat to the occupants thereof shall supply heat to maintain a minimum temperature of 68°F (20°C) in all habitable rooms, bathrooms and toilet rooms. Exception: 1. When the outdoor temperature is below the winter outdoor design temperature for the locality, maintenance of the minimum room temperature shall not be required provide that the heating system is operating at its full design capacity. The winter outdoor design temperature for the locality shall be as indicated in Appendix D of the International Plumbing Code as

adopted and amended by the City.

2. In areas where the average monthly temperature is above 30°F (-1°C), a minimum temperature of 65°F (18°C) shall be maintained.

604.2 Service. The size and usage of appliances and equipment shall serve as a basis for determining the need for additional facilities in accordance with NFPA 70. Dwelling units shall be served by a three-wire, 120/240 volt, single-phase electrical service having a minimum rating of 60 amperes. Exception: Electric service may be maintained if installed lawfully.

605.1 Installation. Electrical equipment, wiring and appliances shall be properly installed and maintained in a safe and approved manner.

605.2 Receptacles. Every habitable space in a dwelling shall contain not less than two separate and remote receptacle outlets. Every laundry area shall contain not less than one grounding-type receptacle or a receptacle with a ground fault circuit interrupter. Every bathroom shall contain not less than one receptacle. Any new bathroom receptacle outlet shall have ground fault circuit interrupter protection. All receptacle outlets shall have the appropriate faceplate cover for the location.



# CASE DOCUMENTATION FOR VIOLATION LETTERS MAILED FOR BSB HEARING [ALL LETTERS ARE MAILED CERTIFIED AND FIRST CLASS]

Case No: B1 Letters, V229763-041524

ADDRESS: 938 MENDOZA ST.
Tax Account No: 4100-0005-0211

Owner(s): CANTU MARIA H. ESTATE OF C/O MARIA C. CHAVEZ IND EXEC.

LAST UPDATED ON: Monday, December 02, 2024

#### LETTERS MAILED from 5/30/2024-5/30/2024

MAILED TO	ASSOCIATION WITH PROPERTY	RETURNED MAIL NOTES
CANTU MARIA H ESTATE OF	DECEASED OWNER	B1 Letter Mailed on 5/30/2024
C/O MARIA C CHAVEZ IND EXEC		a series conservation of series and series are series and series a
6315 VICTORIA		
HOUSTON, TX 77020		
CANTU MARIA H ESTATE OF C/O MARIA C CHAVEZ	DECEASED OWNER	B1 Letter Mailed on 5/30/2024
IND EXE		RETURNED MAIL REC'D 6/11/24-
938 MENDOZA ST		RETURN TO SENDER
CORPUS CHRISTI, TX 78416		REFUSED
		UNABLE TO FORWARD
UNKNOWN HEIRS OF MARIA H. CANTU	UNKNOWN HEIRS OF DECEASED OWNER	B1 Letter Mailed on 5/30/2024
6315 VICTORIA		
HOUSTON, TX 77020		
UNKNOWN HEIRS OF MARIA H CANTU	UNKNOWN HEIRS OF DECEASED OWNER	B1 Letter Mailed on 5/30/2024
938 MENDOZA ST		RETURNED MAIL REC'D 6/11/24-
CORPUS CHRISTI, TX 78416		RETURN TO SENDER
		REFUSED
		UNABLE TO FORWARD
JOSE HERRERA	HEIR	B1 Letter Mailed on 5/30/2024
6315 VICTORIA		
HOUSTON, TX 77020		
JOSE HERRERA	HEIR	B1 Letter Mailed on 5/30/2024
938 MENDOZA ST		RETURNED MAIL REC'D 6/11/24-
CORPUS CHRISTI, TX 78416		RETURN TO SENDER
		REFUSED
		UNABLE TO FORWARD
NAOMI CANTU HERNANDEZ	HEIR	B1 Letter Mailed on 5/30/2024
6315 VICTORIA		, , , , , , , , , , , , , , , , , , , ,

HOUSTON, TX 77020		
NAOMI CANTU HERNANDEZ 938 MENDOZA ST CORPUS CHRISTI, TX 78416	HEIR	B1 Letter Mailed on 5/30/2024 RETURNED MAIL REC'D 6/11/24- RETURN TO SENDER REFUSED UNABLE TO FORWARD
OLGA CANTU ROY 6315 VICTORIA HOUSTON, TX 77020	HEIR	B1 Letter Mailed on 5/30/2024
OLGA CANTU ROY 938 MENDOZA ST CORPUS CHRISTI, TX 78416	HEIR	B1 Letter Mailed on 5/30/2024 RETURNED MAIL REC'D 6/11/24- RETURN TO SENDER REFUSED UNABLE TO FORWARD
OLGA CANTU ROY 12300 FLEMING DR APT 175 HOUSTON, TX 77013	HEIR	B1 Letter Mailed on 5/30/2024 RETURNED MAIL RECD' 6/27/24- RETURN TO SENDER UNCLAIMED UNABLE TO FORWARD
JOSE LUIS CANTU JR 6315 VICTORIA HOUSTON, TX 77020	HEIR	B1 Letter Mailed on 5/30/2024
JOSE LUIS CANTU JR 938 MENDOZA ST CORPUS CHRISTI, TX 78416	HEIR	B1 Letter Mailed on 5/30/2024 RETURNED MAIL REC'D 6/11/24- RETURN TO SENDER REFUSED UNABLE TO FORWARD
JOSE LUIS CANTU JR 254 CAPE COD CORPUS CHRISTI, TX 78412	HEIR	B1 Letter Mailed on 5/30/2024 RETURNED MAIL REC'D 6/11/24- RETURN TO SENDER ATTEMPTED- NOT KNOWN UNALBE TO FORWARD
JUAN C. CANTU 6315 VICTORIA HOUSTON, TX 77020	DECEASED HEIR	B1 Letter Mailed on 5/30/2024
JUAN C CANTU 938 MENDOZA ST CORPUS CHRISTI, TX 78416	DECEASED HEIR	B1 Letter Mailed on 5/30/2024 RETURNED MAIL REC'D 6/11/24- RETURN TO SENDER REFUSED UNABLE TO FORWARD
UNKNOWN HEIRS OF JUAN C. CANTU	UNKNOWN HEIRS OF DECEASED HEIR	B1 Letter Mailed on 5/30/2024

6315 VICTORIA		
HOUSTON, TX 77020		
UNKNOWN HEIRS OF JUAN C CANTU 938 MENDOZA ST CORPUS CHRISTI, TX 78416	UNKNOWN HEIRS OF DECEASED HEIR	B1 Letter Mailed on 5/30/2024 RETURNED MAIL REC'D 6/11/24- RETURN TO SENDER REFUSED UNABLE TO FORWARD
MARY ESTER CANTU CHAVEZ 6315 VICTORIA HOUSTON, TX 77020	HEIR	B1 Letter Mailed on 5/30/2024
MARY ESTER CANTU CHAVEZ 938 MENDOZA ST CORPUS CHRISTI, TX 78416	HEIR	B1 Letter Mailed on 5/30/2024 RETURNED MAIL REC'D 6/11/24- RETURN TO SENDER REFUSED UNABLE TO FORWARD
ROY CANTU AKA ROGELIO CANTU 6315 VICTORIA HOUSTON, TX 77020	HEIR	B1 Letter Mailed on 5/30/2024
ROY CANTU AKA ROGELIO CANTU 938 MENDOZA SR CORPUS CHRISTI, TX 78416	HEIR	B1 Letter Mailed on 5/30/2024 RETURNED MAIL REC'D 6/11/24- RETURN TO SENDER REFUSED UNABLE TO FORWARD
ROY CANTU AKA ROGELIO CANTU 1118 MENDOZA ST CORPUS CHRISTI, TX 78416	HEIR	B1 Letter Mailed on 5/30/2024 RETUREND GREEN CARD REC'D 6/6/24- SIGNED BY CANTU
JESSE F. CANTU AKA JESUS FRANCISCO CANTU 6315 VICTORIA HOUSTON, TX 77020	HEIR	B1 Letter Mailed on 5/30/2024
JESSE F CANTU AKA JESUS FRANCISCO CANTU 938 MENDOZA SR CORPUS CHRISTI, TX 78416	HEIR	B1 Letter Mailed on 5/30/2024 RETURNED MAIL REC'D 6/11/24- RETURN TO SENDER REFUSED UNABLE TO FORWARD
JESSE F CANTU AKA JESUS FRANCISCO CANTU 11203 SAM NAIL RANCH SAN ANTONIO, TX 78245	HEIR	B1 Letter Mailed on 5/30/2024 RETURNED MAIL REC'D 6/24/24- RETURN TO SENDER UNCLAIMED UNALBE TO FORWARD
ARTURO C. CANTU AKA CLEMENTE ARTURO CANTU	HEIR	B1 Letter Mailed on 5/30/2024

6315 VICTORIA		
HOUSTON, TX 77020		
ARTURO C CANTU AKA CLEMENTE ARTURO CANTU	HEIR	B1 Letter Mailed on 5/30/2024
938 MENDOZA ST		RETURNED MAIL REC'D 6/11/24-
CORPUS CHRISTI, TX 78416		RETURN TO SENDER
		REFUSED
		UNABLE TO FORWARD
ARTURO C. CANTU AKA CLEMENTE ARTURO CANTU	HEIR	B1 Letter Mailed on 5/30/2024
1704 BOSTIC ST.		== 25355 Maried 511 5/55/252-1
HOUSTON, TX. 77093-7424		
MARGIE CANTU CERTUCHE AKA MARGARITA CANTU	HEIR	B1 Letter Mailed on 5/30/2024
ZERTUCHE	The state of the s	bi Letter Maileu on 5/50/2024
6315 VICTORIA		
HOUSTON, TX 77020		
MARGIE CANTU CERTUCHE AKA MARGARITA CANTU	HEIR	P4
ZERTUCHE	HEIK	B1 Letter Mailed on 5/30/2024
938 MENDOZA ST		RETURNED MAIL REC'D 6/11/24-
		RETURN TO SENDER
CORPUS CHRISTI, TX 78416		REFUSED
		UNABLE TO FORWARD
MARGIE CANTU CERTUCHE AKA MARGARITA CANTU	HEIR	B1 Letter Mailed on 5/30/2024
ZERTUCHE		
3615 ITASKA CTS		
CORPUS CHRISTI, TX 78415		
ROSEMARY CANTU SALAZAR AKA ROSE MARY	HEIR	B1 Letter Mailed on 5/30/2024
SALAZAR		, , , , , , , , , , , , , , , , , , ,
6315 VICTORIA		
HOUSTON, TX 77020		
ROSEMARY CANTU SALAZAR AKA ROSE MARY	HEIR	B1 Letter Mailed on 5/30/2024
SALAZAR		RETURNED MAIL REC'D 6/11/24-
938 MENDOZA ST		RETURN TO SENDER
CORPUS CHRISTI, TX 78416		
2011 03 CHRISTI, 17 70410		REFUSED
ROSEMARY CANTU SALAZAR AKA ROSE MARY	HEID	UNABLE TO FORWARD
SALAZAR	HEIR	B1 Letter Mailed on 5/30/2024
		RETURNED GREEN CARD REC'D 6/6/24-
6343 CRESTSIDE DR		SIGNED BY UNREADABLE
PASADENA, TX 77505		
MARY CANTU HINOTE AKA MARIA GUADALUPE	HEIR	B1 Letter Mailed on 5/30/2024
HINOTE		
6315 VICTORIA		
HOUSTON, TX 77020		

MARIA CANTU HINOTE AKA MARIA GUADALUPE HINOTE 938 MENDOZA ST CORPUS CHRISTI, TX 78416	HEIR	B1 Letter Mailed on 5/30/2024 RETURNED MAIL REC'D 6/11/24- RETURN TO SENDER REFUSED UNABLE TO FORWARD
MARIA CANTU HINOTE AKA MARIA GUADALUPE HINOTE 24032 MISTY LAKE CIR NEW CANEY, TX 77357	HEIR	B1 Letter Mailed on 5/30/2024
UNKNOWN HEIRS OF JOSE HERRERA 6315 VICTORIA HOUSTON, TX. 77020	UNKNOWN HEIRS OF DECEASED HEIR	B1 Letter Mailed on 12/2/2024
UNKNOWN HEIRS OF JOSE HERRERA 938 MENDOZA ST CORPUS CHRISTI, TX 78416	UNKNOWN HEIRS OF DECEASED HEIR	B1 Letter Mailed on 12/2/2024
UNKNOWN HEIRS OF JOSE LUIS CANTU JR 6315 VICTORIA HOUSTON, TX. 77020	UNKNOWN HEIRS OF DECEASED HEIR	B1 Letter Mailed on 12/2/2024
UNKNOWN HEIRS OF JOSE LUIS CANTU JR 938 MENDOZA ST CORPUS CHRISTI, TX 78416	UNKNOWN HEIRS OF DECEASED HEIR	B1 Letter Mailed on 12/2/2024