



5117 MARGARET AVE- RESIDENTIAL & ACCESSORY STRUCTURE

- Substandard case started 4/8/2025.

Structure deemed substandard based on the following findings:

- Structure does not meet the minimum requirements and standards as set forth in the International Property Maintenance Code.
- Exterior of the structure is not in good repair, is not structurally sound, and does not prevent the elements or rodents from entering the structure.
- Interior of the structure is not in good repair, is not structurally sound, and is not in a sanitary condition.
- Structure is unfit for human occupancy and found to be dangerous to the life, health, and safety of the public.

City Recommendation: Demolition of residential and accessory structure (Building Survey attached)

Property located in a residential area and a main thoroughfare street. (Navigation Blvd)

According to NCAD, Alvarez Francisco G Etals took possession of property 1/2/2001.

Case, Abatement, and Citation History

Total number of Code complaints: 2

Total number of cases: 9

Owner Compliance: 4

City Abatements: 1

Citations issued: 3



5117 MARGARET AVE- RESIDENTIAL & ACCESSORY STRUCTURE

Date	Case Type	Violation(s)	Status
1/9/2020	Care of Premises	Section 23-70 TALL WEEDS & Section 22-6 LITTER AND SOLID WASTE	Compliant
2/26/2021	Care of Premises	Section 23-70 TALL WEEDS & Section 22-6 LITTER AND SOLID WASTE	Closed
2/26/2021	PMC Standards	304.1 Exterior Structure/General 304.6 Exterior Walls 304.7 Roofs and Drainage	Closed
9/13/2024	Care of Premises	Section 23-70 TALL WEEDS, BRUSH, AND DISEASED TREES PROHIBITED ON LOTS Section 22-6 LITTER AND SOLID WASTE Section 49-10 KEEP SIDEWALKS, CURBS, AND GUTTERS	Closed
12/9/2024	Junked Vehicle	Section 13-38 JUNKED VEHICLES	Compliant
12/9/2024	Junked Vehicle	Section 13-38 JUNKED VEHICLES	Compliant
4/8/2025	Vacant Building	Section 23-70 TALL WEEDS, BRUSH, AND DISEASED TREES PROHIBITED ON LOTS Section 22-6 LITTER AND SOLID WASTE	In Progress
4/8/2025	Unsecured Vacant Building	Section 13-3008 DUTY TO SECURE VACANT BUILDING	In Progress
4/10/2025	Substandard Structure	108.1.3 Structure Unfit for Human Occupancy	In Progress

Abatement history for 5117 Margaret Ave.

<u>Date</u>	<u>Cost/Admin Fee</u>	<u>Case Type</u>
1/10/2025	\$401.13/\$412.00	Tall Weeds

Total: \$813.13



5117 MARGARET AVE- RESIDENTIAL & ACCESSORY STRUCTURE

CCPD calls to property:

Nature of Call	5117 Margaret Ave.
LAW ENFORCEMENT ASSIST	1
CIVIL MATTER/STANDBY	2
FIREWORKS POSSESSION OR USE	1
LAW ENFORCEMENT INVESTIGATION	1
NOISE ORDINANCE VIOLATION	2
QUALITY OF LIFE	1
TELEPHONE REPORTING UNIT	1
Grand Total	9

Attempted contact with Property Owner(s)

DATE	NAME	CONTACT DETAILS
	FRANCISCO G ALVAREZ	OWNER IS DECEASED
5/1/2025	JIM PERKINS	SPOKE WITH JIM PERKINS AT (361) 595-6762. HE SAID THAT HE WOULD SECURE IT TODAY
4/21/2025	JIM PERKINS	SPOKE WITH JIM PERKINS AT (361) 595-6762. HE IS THE GANDSON-IN-LAW TO THE DECEASED PROPERTY OWNER. HE SAID THAT HE WOULD TAKE CARE OF THE ISSUES.
7/16/2021	JAMES PERKINS	RECEIVED VOICEMAIL FROM JAMES PERKINS STATING THAT THEY HAVE AN UPCOMING COURT DATE FOR THE CITATION WRITTEN.
2/25/2020	Resident	MADE CONTACT WITH RESIDENT WHO INFORMED ME THAT SOMEONE WAS COMING OUT TO CLEAN UP PROPERTY TODAY AND WOULD HAVE IT CLEANED UP. REQUESTED EXTENSION. GRANTED 1 WEEK EXTENSION.

11/3/2025

Code Compliance Supervisor: Roland Maldonado

Case# V254848-041025

Property Owner: ALVAREZ FRANCISCO G ETALS

Address (☒Residential ☐Commercial): 5117 MARGARET AVE

Staff Recommendation(s): **Demolition**

☐Residential Structure only

☒Residential and Accessory Structure

☐Commercial Structure only

☐Commercial and Accessory Structure

Under the provisions of Section 13-22 (H)(1)(c) of the Corpus Christi Property Maintenance Code and due to substandard and dilapidated condition of the structure(s), a hazard to the health, safety, and welfare of the public is henceforth declared.

Therefore, the owner be required to **demolish** the residential & accessory structure(s) within thirty (30) days. If demolition is not started and completed as required, then the City be authorized to demolish.

Notices

1. Letters of substandard conditions sent by certified mail.
2. Final notice sent by certified mail.
3. Certified letter of hearing sent by certified mail
4. Notice of hearing published in newspaper.

Additional

1. Owner Deceased: ☐ No ☒ Yes If deceased verification by: ☒Obituary ☐Death Certificate
2. Structure Entered by: ☐Search Warrant ☐Consent Given by: Owner ☒Unsecure
3. Taxes due: ☒ Current ☐Past due -Amount owed:
4. Utilities: ☐Active ☒Inactive-Last active date: 6/3/2014
5. Year Structure Built: 1950
6. Lawsuits: ☐Yes ☒No
7. Code Enforcement Maintaining Property: ☒Yes ☐No

COMPLAINT

Monday October 27, 2025

Building Standards Board
City of Corpus Christi
2406 Leopard St.
Corpus Christi, Texas 78408

RE: 5117 MARGARET AVE (Residential & Accessory Structure) Case # V254848-041025

OWNER: Alvarez Francisco G Etals


**Code Compliance Supervisor
Roland Maldonado**

Dear Board Members:

Pursuant to Article II and in accordance with Section 13-22(B), of the Corpus Christi Property Maintenance Code, this Department has initiated and prepared the above listed case for your review and consideration. On **April 8, 2025**, the code official determined that there were reasonable grounds to believe there was a violation(s) of the Corpus Christi Property Maintenance Code or any rule or regulation concerning the health, safety, or general welfare adopted by the city as it relates to structures or premises and gave notice of such alleged violation to the owner of the property. Thirty days have elapsed since the notice of violation(s) was provided and such violation(s) have not been cured.

Staff recommends a hearing be set for not less than ten (10) days or more than forty-five (45) days from the date of this complaint. At this hearing staff recommendation for the above listed property will be repair/**demolition**.

If you have any questions concerning the above, please call (361) 826-3046.




Roland Maldonado
Supervisor
Development Services
Code Compliance Division

cc: Carlos Martinez, John Solberg, Merced V. Pena, William B. Ewing Jr,
Chic G. Henderson, Lynne Hurlburt

CASE TIMELINE FOR 5117 MARGARET AVE.


Activity	Date	Legal Requirement	Legal Reference
Code Enforcement Notified of Potential Violation	4/8/2025	n/a	n/a
Initial Inspection Completed	4/8/2025	When building, structure or premise thought to be substandard	Corpus Christi Property Maintenance Code 104.2
Notice of Violation Mailed to Last Known Addresses	4/11/2025	When there are reasonable grounds to believe there is a violation	City Ordinance Sec. 13-22(A) & (D)(2)
Notice of Violation Posted in Newspaper	7/29/2025 & 7/30/2025	When owner is unknown, whereabouts unknown, or where service of notice has failed (Published twice w/in a 10 day period)	City Ordinance Sec.13-22(A) & (D)(3)
Deadline to comply with Newspaper Notice of Violation	8/1/2025	When 30 days have elapsed from the date of first publication	City Ordinance Sec. 13-22(B)
Notice Received	4/21/2025	Return mail rec'vd 4/21/2025 return to sender,vacant, unable to forward	n/a
Returned Notice of Violation Posted at Front Door of Property	8/4/25-5/30/25 & 6/2/25-6/6/25	When notice is returned showing unclaimed or not delivered	City Ordinance Sec. 13-22(A) & (D)(4)
Deadline to comply with Mailed Notice of Violation	5/20/2025	30 days from receipt of the notice	City Ordinance Sec. 13-22(A)(5)
Re-inspection	8/1/2025	Not less thans 30 days from receipt of the notice or when 30 days have elapsed from date of first publication	City Ordinance Sec. 13-22(B)
Complaint filed with BSB	10/27/2025	When owner refused to comply; when not cured within 30 days from receipt of notice or any further agreed time; or when 30 days have elapsed from date of first publication	City Ordinance Sec. 13-22(B)(2)
Notice of Hearing Mailed to Last Known Address	10/28/2025	At least 10 days prior to hearing	City Ordinance Sec. 13-22(C) & (D)(2)
Notice of Hearing Posted in Newspaper	10/27/2025 & 10/28/2025	At least 10 days prior to hearing when owner is unknown, whereabouts unknown, or where service of notice has failed (Published twice w/in a 10 day period)	City Ordinance Sec.13-22(C) & (D)(3)
Notice of Hearing Filed with County Clerk	10/27/2025	At least 10 days prior to hearing	City Ordinance Sec. 13-22(C) & Tx Local Gov't Code 214.001€
Returned Notice of Hearing Posted at Front Door of Property	11/10/25-11/14/25 & 11/17/25-11/19/25	When notice is returned showing unclaimed or not delivered	City Ordinance Sec. 13-22(C) & (D)(4)
BSB Agenda Posted	11/14/2025	72 hours (3 days) before scheduled time of hearing	Texas Govt. Code 551.043(a)
BSB Hearing	11/20/2025	Not less than 10 days nor more than 45 days after Complaint filed	City Ordinance Sec. 13-22 (C)






5117 MARGARET


Aerial View


















City of Corpus Christi – BUILDING SURVEY

Account Number: 957900010030

Inspection Date: 4/8/25

Zoning Use: IL

Revised Date: 04/10/2025

Officer: MICHAEL GUTIERREZ

Property Address: 5117 MARGARET AVE

Legal Description: WHELAN ADD E25' OF LT 2 & W25' OF LT 3 BK 1

Owner: ALVAREZ FRANCISCO G ETALS

Mail to: 5117 MARGARET

City, State, Zip: CORPUS CHRISTI, TX 78407

☒ Dwelling ☐ Commercial ☒ Accessory 7,500 Sq. Ft. 1 _____ Story
☒ Wood Frame ☐ Masonry ☐ Fire Damage 1 _____ # of Units ☒ Inside Inspection
☒ Vacant ☐ Occupied ☒ Open ☐ Placard
Placard Posted on:

Corrections must be made to the item(s) checked below to comply with the Corpus Christi Property Maintenance Code and/or ordinances of the City of Corpus Christi. The following city ordinances are applicable: Building, Plumbing, Electrical, Mechanical, Fire, Health and Zoning.

Permits Required:

☒ Building ☒ Plumbing ☒ Electrical ☐ Mechanical
☐ Fire ☐ Health ☐ Other:

Smoke Alarms:

☒ Missing ☐ Inoperative ☐ Improperly Located ☐ Additional Alarms Required

OUTSIDE WALL:

(304.1, 304.2 304.4 & 304.6)

Type:

☐ Charred Wood
☒ Rotten Wood
☒ Rotten Corner Boards
☒ Missing Boards
☐ Badly in Need of Paint
☒ Siding Broken / Missing
☒ Holes
☒ Cracks
☐ Buckled
☐ Leans
☐ Missing Brick
☐ Loose Brick
☐ Damaged Exterior Trim
☐ Other:

ROOF:

(304.1 & 304.7)

Type:

☐ Charred Wood
☒ Rotten Eaves
☒ Rotten Rafter Tails
☒ Rotten Decking
☒ Missing Shingles
☒ Deteriorated Shingles
☒ Leaks
☐ Sags
☐ Buckled
☐ Collapsed
☐ Worn
☐ Torn
☒ Holes
☐ Other:

FOUNDATION:

(304.1, 304.4 & 304.5)

Type:

☐ Inadequate Support
☒ Rotten Wood
☐ Piers Lean
☒ Piers Missing
☒ Cracks/Perimeter Wall
☒ Cracks/Slab
☐ Pads Missing/Cracked
☐ Missing Skirting
☐ Missing Access Cover
☒ Exposed Sills
☒ Rotten Sills
☒ Damaged Floor Joist
☒ Sagging Floor Joist
☐ Other:

WINDOWS: (304.1, 304.2 304.13,
304.13.1, 304.13.2, 304.14 &
304.17)

☐ Charred Wood
☒ Broken Glass
☒ Missing Screens
☐ Torn Screens
☐ Missing / Broken Sash
☐ Do Not Open
☒ Rotten Sills
☒ Rotten / Broken Frames
☐ Other:

PORCHES: (304.1, 304.2, 304.10,
304.12, 305.4, 305.5 & 307.1)

☐ Charred Wood
☒ Missing / Broken Boards
☒ Loose
☒ Rotten Wood
☒ Inadequate Support
☐ Support Post Missing
☐ Support Post Loose
☐ Faulty Weather Protection
☐ Other:

DOORS: (304.1, 304.2, 304.13,
304.14, 304.15, 304.16, 304.18,
305.6 & 702.1)

☐ Charred Wood
☒ Missing
☒ Damaged
☐ Poor Fit
☒ Damaged / Missing Screen(s)
☒ Off Hinges
☐ Blocked Exit
☐ Rotten
☐ Other:

STEPS: (304.1, 304.2
304.10, 304.12, 305.4 & 305.5)

☐ Charred Wood
☐ Rotten Wood
☐ Missing Boards
☐ Inadequate Support
☐ Missing Handrails
☐ Faulty Weather Protection
☐ Other:

PLUMBING: BATHTUB / SHOWER(403.2, 502.1, 502.2, 502.3, 504.1, 504.2, 504.3, 505.1.1,
& 505.3)

☐ Missing
☒ Faucets Loose / Broken / Missing
☐ No Anti-Siphon Faucets
☐ Missing Overflow Plate
☐ Missing Tap
☐ Missing Shower Head
☐ Not Vented
☒ Disconnected
☐ Stopped Up
☐ Damaged Shower Stall
☐ Other:

PLUMBING: WATER CLOSET(404.4.3, 502.1, 502.2, 502.3, 502.4, 503.1, 503.4,
504.1, 504.2, 504.3, 505.1.1, 506.1 & 506.2)

☐ Missing
☐ No Anti-Siphon Ballcock
☐ Stopped Up
☐ Poorly Anchored
☐ Seeps Around Bowl
☐ Water Supply Line Leaks
☐ Flush Ell Leaks
☐ Runs Constantly
☐ Tank Broken / Cracked
☐ Bowl Broken / Cracked
☒ Disconnected
☐ Missing Flush Handle
☐ Missing Flapper
☐ Urinal; No Back-Flow Preventive
☐ No Elongated Bowl / Open-end Seat
☐ Other:

WATER HEATER:

(505.4, 603.1, 603.2, 603.3, 603.4 603.5 & 603.6)

☒ Gas
☐ Electric
☐ Missing
☒ Disconnected
☐ Temperature Pressure Release Valve Missing
☐ Temperature Pressure Release Valve Broken
☐ Drain Line Missing
☐ Not Approved Pipe
☐ Not Extended Outside
☐ Elbowed Down
☐ Vent Missing / Loose
☐ No Double Wall Pipe / Attic
☐ Nonconforming Vent
☐ Inadequate Combustion Air
☐ Thermostat Missing / Damaged
☐ No Gas Cut Off
☐ Missing Firebox Door
☐ Gas Supply Line Not Approved Pipe
☐ Gas Fired – Located in Bathroom
☐ Gas Fired – Located in Bedroom
☐ Fire Damaged
☐ Other:

SYSTEM:

(604.3.2, 604.3.2.1, 605.1, 605.2 & 605.3)

- ☐ Burned Wiring / Plugs / Switches
- ☐ Burned Fixtures
- ☐ Less Than 1 Duplex Recept. /20 liner ft-
- ☐ Bedroom/Living Rm/Dining Rm/Den/Kitchen
- ☐ No Small Appliance Circuits Over Kitchen
- ☐ Counter Space with GFCI
- ☐ Only One Small Appliance Circuit Over Kitchen
- ☐ Counter Space with NO GFCI
- ☐ Kitchen Appliance Circuits – No GFCI
- ☐ Plugs Missing / Loose / Broken
- ☐ Switches Missing / Loose / Broken
- ☐ Fixtures Missing / Loose / Broken
- ☐ Missing Switch Cover / Plug Covers
- ☐ Extension Cords in Place of Permanent Wiring
- ☐ Bathroom Circuit NO GFCI
- ☐ Conduit Broken / Loose / Missing
- ☐ No Separate Circuit For
- ☐ No Disconnect for Air Conditioner
- ☐ Exterior Lights Missing; Front / Back / Side
- ☐ Porch Lights Broken / Missing / Loose
- ☐ Other:

INTERIOR FLOORS:

(305.1, 305.2, 305.3 & 305.4)

- ☐ Charred Wood
- ☒ Rotten Wood
- ☒ Missing Boards
- ☒ Holes
- ☒ Cracks
- ☐ Not Level
- ☐ Buckled
- ☐ Torn
- ☒ Damaged
- ☐ Other:

MECHANICAL:

(403.1, 403.2, 603.1 & 603.6)

- ☐ Vented Wall Heater Damaged / Missing
- ☐ Floor Furnace Damaged / Missing
- ☐ Nonconforming Gas Line to Space Heater
- ☐ Wall Heater with No Vent in Bathroom
- ☐ Thermostat Damaged / Missing
- ☐ Gas-Fired Heating Appliance within 2' of
- ☐ Tub / Shower / Water Closet
- ☐ Condensing Unit Damaged / Missing
- ☐ No Vent Fan or Window in Bathroom
- ☐ Vent Fan Missing / Not Operable
- ☐ Heat with No Vent in Commercial Building
- ☐ Fire Damage
- ☐ Other:

ACCESSORY SURVEY:

(302.7, 304.1, 304.2, 304.4, 304.5, 304.6 & 305.2)

- TYPE: GARAGE
- ☐ Roof Type: ALUMINUM
- ☐ Rotten
- ☒ Loose
- ☐ Torn
- ☒ Holes
- ☒ Missing
- ☐ Walls Type:
- ☒ Rotten
- ☐ Leaning
- ☐ Buckled
- ☐ Missing
- ☐ Other:

UNSANITARY CONDITIONS:

(308.3, 309.1, 504.1 & 505.1.2)

- ☒ No Hot and Cold Water Supply
- ☐ Insect, Roach, Rodent Infestation
- ☐ Lacks Adequate Garbage Containers
- ☐ Other:

- ☐ Foundation Type:
- ☐ Sunken
- ☐ Rotten Sills
- ☐ Other:

LAVATORY: (404.4.3, 502.1, 502.2, 502.3
502.4, 504.1, 504.2, 504.3, 505.1.1,
506.1 & 506.2)

- ☐ Missing
- ☐ No Anti-Siphon Faucets
- ☐ Faucets Leak / Broken / Missing
- ☐ "P" Trap Leaks / Missing
- ☐ Defective Trap
- ☐ Stopped Up
- ☐ Water Supply Line Leak
- ☐ Loose from Wall
- ☐ Nonconforming Waste Line
- ☒ Disconnected
- ☐ Other:

KITCHEN SINK: (305.1, 305.3, 502.1,
505.1.1, 506.1 & 506.2)

- ☐ Defective Trap
- ☐ Faucets Loose / Broken
- ☐ Faucets Missing
- ☐ "P" Trap Rubber Hose
- ☐ Trap Leaks / Missing
- ☐ Stopped Up
- ☒ Disconnected
- ☒ Damaged Counter Top
- ☐ Damaged Back Splash
- ☐ Other:

ELECTRICAL SERVICE: (604.1, 604.2
604.3, 604.3.1, 604.3.1.1, 604.3.2, 604.3.2.1
605.1, 605.2 & 605.3)

- ☐ Service Panel Burned
- ☐ Service Missing
- ☐ Service Appears Below Code
- ☐ Two-Wire Service
- ☐ Inadequate
- ☐ Defective
- ☐ Disconnected
- ☐ Service Not Grounded
- ☐ Missing Breakers / Fuses
- ☐ Missing Interior / Exterior Panel Cover
- ☐ Exposed Wiring
- ☐ Nonconforming Wiring in Panel
- ☐ Drops Too Low
- ☐ Other:

GAS SYSTEM: (602.1, 602.2, 602.3, 602.5
603.1, 603.2, 603.3, 603.4, 603.5 & 603.6)

- ☐ Gas Pressure Test Required
- ☐ Gas Leak
- ☐ Line Appears to Enter Building Below Grade Level
- ☐ Gas Supply Not Approved Pipe
- ☐ Rubber Hose to Space Heaters
- ☐ Non-Rigid Pipe Run Through Partition Wall
- ☐ Other:

PLUMBING MISCELLANEOUS:

(504.1, 504.2, 504.3, 505.3, 506.2 & 507.1)

- ☐ Open Clean Out / Water Leak; Yard / Under House
- ☐ Vent Stack Missing / Broken
- ☐ Vent Stack Not Extended Through Roof
- ☐ Rain Guard Damaged / Missing
- ☐ Exposed Exterior PVC Pipe
- ☐ PVC Water Supply Lines
- ☐ Washer No "P" Trap / Not Vented / Not Cut Offs
- ☐ Sewer Line Stopped Up
- ☐ Sewer Running Out on Ground
- ☐ Other:

INSIDE WALLS AND CEILINGS:

(305.1, 305.2, 305.3 & 404.3)

- ☐ Charred Wood
- ☐ Paint Deteriorated
- ☒ Cracks
- ☒ Holes
- ☐ Torn Wallpaper
- ☒ Damaged Paneling
- ☒ Sheetrock Broken / Missing / Holes, 506.1 & 506.2
- ☐ Sheetrock Mildewed / Buckled
- ☒ Ceiling Damaged / Missing
- ☐ Water Damaged / Smoke Damaged
- ☐ Impervious Material Around Tub
- ☐ Enclosure Damaged / Missing
- ☐ Walls Around Tub Not Water Resistant
- ☐ Inadequate Ceiling Height
- ☐ Other:

VIOLATION(S):

108.1.3 Structure unfit for human occupancy. A structure is unfit for human occupancy whenever the code official finds that such structure is unsafe, unlawful or, because of the degree to which the structure is in disrepair or lacks maintenance, is insanitary, vermin or rat infested, contains filth and contamination, or lacks ventilation, illumination, sanitary or heating facilities or other essential equipment required by this code, or because the location of the structure constitutes a hazard to the occupants of the structure or to the public.

108.1.5 Dangerous structure or premises. For the purpose of this code, any structure or premises that has any or all of the conditions or defects described below, but which is not limited to those described below, shall be considered dangerous and may be deemed substandard:

1. Any door, aisle, passageway, stairway, exit or other means of egress that does not conform to the approved building or fire code of this City as related to the requirements for existing buildings.
2. The walking surface of any aisle, passageway, stairway, exit or other means of egress is so warped, worn loose, torn or otherwise unsafe as to not provide safe and adequate means of egress.
3. Any portion of a building, structure or appurtenance that has been damaged by fire, earthquake, wind, flood, deterioration, neglect, abandonment, vandalism or by any other cause to such an extent that it is likely to partially or completely collapse, or to become detached or dislodged, or which cannot be expected to withstand winds of hurricane force.
4. Any portion of a building, or any member, appurtenance or ornamentation on the exterior thereof that is not of sufficient strength or stability, or is not so anchored, attached or fastened in place so as to be capable of resisting natural or artificial loads of one and one-half the original designed value.
5. The building or structure, or part of the building or structure, because of dilapidation, deterioration, decay, faulty construction, the removal or movement of some portion of the ground necessary for the support, or for any other reason, is likely to partially or completely collapse, or some portion of the foundation or underpinning of the building or structure is likely to fail or give way.
6. The building or structure, or any portion thereof, is clearly unsafe for its use and occupancy.
7. The building or structure is neglected, damaged, dilapidated, unsecured or abandoned so as to become an attractive nuisance to children who might play in the building or structure to their danger, becomes a harbor for vagrants, criminals or immoral persons, or enables persons to resort to the building or structure for committing a nuisance or an unlawful act.
8. Any building or structure has been constructed, exists or is maintained in violation of any specific requirement or prohibition applicable to such building or structure provided by the approved building or fire code of the jurisdiction, or of any law or ordinance to such an extent as to present either a substantial risk of fire, building collapse or any other threat to life and safety.
9. A building or structure, used or intended to be used for dwelling purposes, because of inadequate maintenance, dilapidation, decay, damage, faulty construction or arrangement, inadequate light. Ventilation, electrical, mechanical, or plumbing system, or otherwise, is determined by the code official to be insanitary, unfit for human habitation or in such a condition that is likely to cause sickness or disease, including all conditions conducive to the harboring of rats or mice or other disease-carrying animals or insects reasonably calculated to spread disease.
10. Any building or structure, because of a lack of sufficient or proper fire- resistance-rated construction, fire protection systems, electrical system, fuel connections, mechanical system, plumbing system or other cause, is determined by the code official to be a threat to life or health.
11. All buildings or structures which have pit privies where the same are not permitted by law or which are not connected to the city sewer when required by law or where inadequate and unsanitary pit privies or septic tanks exist.
12. Any portion of a building remains on a site after the demolition or destruction of the building or structure or whenever any building or structure is abandoned so as to constitute such building or portion thereof as an attractive nuisance or hazard to the public.

304.1 General. The exterior of a structure shall be maintained in good repair, structurally sound and sanitary so as not to pose a threat to the public health, safety or welfare.

304.10 Stairways, decks, porches and balconies. Every exterior stairway, deck, porch and balcony, and all appurtenances attached thereto, shall be maintained structurally sound, in good repair, with proper anchorage and capable of supporting the imposed loads.

304.13 Window, skylight and door frames. Every window, skylight, door and frame shall be kept in sound condition, good repair and weather tight.

304.15 Doors. Exterior doors, door assemblies, operator systems if provided, and hardware shall be maintained in

good condition. Locks at all entrances to dwelling units and sleeping units shall tightly secure the door. Locks on means of egress doors shall be in accordance with Section 702.3.

304.4 Structural members. Structural members shall be maintained free from deterioration, and shall be capable of safely supporting the imposed dead and live loads.

304.5 Foundation. All foundations, piers, or other structural elements shall be maintained plumb and capable of adequate support, free from open cracks and breaks and shall be kept in such condition so as to prevent the entry of rodents and other pests.

304.6 Exterior walls. Exterior walls shall be free from holes, breaks, and loose or rotting materials; and maintained weatherproof and properly surface coated where required to prevent deterioration.

304.7 Roofs and drainage. The roof and flashing shall be sound, tight and not have defects that admit rain. Roof drainage shall be adequate to prevent dampness or deterioration in the walls or interior portion of the structure. Roof drains, gutters and downspouts shall be maintained in good repair and free from obstructions. Roof water shall not be discharged in a manner that creates a public nuisance.

305.1 General. The interior of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. Occupants shall keep that part of the structure which they occupy or control in a clean and sanitary condition. Every owner of a structure containing a rooming house, housekeeping units, a hotel, a dormitory, two or more dwelling units or two or more nonresidential occupancies, shall maintain, in a clean and sanitary condition, the shared or public areas of the structure and exterior property.

305.2 Structural members. Structural members shall be maintained structurally sound, and be capable of supporting the imposed loads.

305.4 Stairs and walking surfaces. Every stair, ramp, landing, balcony, porch, deck or other walking surface shall be maintained in sound condition and good repair.

305.6 Interior doors. Every interior door shall fit reasonably well within its frame and shall be capable of being opened and closed by being properly and securely attached to jambs, headers or tracks as intended by the manufacturer of the attachment hardware.

503.4 Floor surface. In other than dwelling units, every toilet room floor shall be maintained to be a smooth, hard, nonabsorbent surface to permit such floor to be easily kept in a clean and sanitary condition.

505.1.2 Hot and Cold Water Supply: All kitchen sinks, lavatories, laundry facilities, bathtubs and showers shall be supplied with hot or tempered and cold running water in accordance with the International Plumbing Code as adopted and amended by the City.

Exceptions: Facilities constructed lawfully without hot water.



CASE DOCUMENTATION FOR VIOLATION LETTERS MAILED FOR BSB HEARING

[ALL LETTERS ARE MAILED CERTIFIED AND FIRST CLASS]

Case No: B1 Letters, V254848-041025

ADDRESS: 5117 MARGARET AVE

Tax Account No: 9579-0001-0030

LAST UPDATED ON: Monday, May 05, 2025

Owner(s): ALVAREZ FRANCISCO G ETALS

LETTERS MAILED from 4/11/2025-4/11/2025

MAILED TO	ASSOCIATION WITH PROPERTY	RETURNED MAIL NOTES
ALVAREZ FRANCISCO G ETALS 5117 MARGARET CORPUS CHRISTI, TX 78407	Owner	B1 Letter Mailed on 4/11/2025 RETURN MAIL REC'VD 4/21/2025 RETURN TO SENDER VACANT UNABLE TO FORWARD
UNKNOWN HEIRS OF FRANCISCO ALVAREZ 5117 MARGARET AVE CORPUS CHRISTI, TX 78407	Deceased Owner Uknown Heirs	B1 Letter Mailed on 4/11/2025 RETURN MAIL REC'VD 4/21/2025 RETURN TO SENDER VACANT UNABLE TO FORWARD
ANDREA C. ALVAREZ 5117 MARGARET AVE CORPUS CHRISTI, TX 78407	Heir	B1 Letter Mailed on 4/11/2025 RETURN MAIL REC'VD 4/21/2025 RETURN TO SENDER VACANT UNABLE TO FORWARD
UNKNOWN HEIRS OF ANDREA C. ALVAREZ 5117 MARGARET AVE CORPUS CHRISTI, TX 78407	Deceased Heirs of Deceased Heir	B1 Letter Mailed on 4/11/2025 RETURN MAIL REC'VD 4/21/2025 RETURN TO SENDER VACANT UNABLE TO FORWARD
LUPITA FUENTES ALVAREZ 5117 MARGARET AVE CORPUS CHRISTI, TX 78407	Heir	B1 Letter Mailed on 4/11/2025 RETURN MAIL REC'VD 4/21/2025 RETURN TO SENDER VACANT UNABLE TO FORWARD
JASON FUENTES	Heir	B1 Letter Mailed on 4/11/2025

5117 MARGARET AVE CORPUS CHRISTI, TX 78407		RETURN MAIL REC'VD 4/21/2025 RETURN TO SENDER VACANT UNABLE TO FORWARD
CELIA FLORES 5117 MARGARET AVE CORPUS CHRISTI, TX 78407	Heir	B1 Letter Mailed on 4/11/2025 RETURN MAIL REC'VD 4/21/2025 RETURN TO SENDER VACANT UNABLE TO FORWARD
ESPERANZA FUENTEZ 5117 MARGARET AVE CORPUS CHRISTI, TX 78407	Heir	B1 Letter Mailed on 4/11/2025 RETURN MAIL REC'VD 4/21/2025 RETURN TO SENDER VACANT UNABLE TO FORWARD
ANDREA C. ALVAREZ PO BOX 513 KINGSVILLE, TX. 78364	Heir	B1 Letter Mailed on 4/11/2025 RETURN MAIL REC'VD 5/5/2025 RETURN TO SENDER VACANT UNABLE TO FORWARD
UNKNOWN HEIRS OF ANDREA C. ALVAREZ PO BOX 513 KINGSVILLE, TX. 78364	Deceased Heirs of Deceased Heir	B1 Letter Mailed on 4/11/2025 RETURN MAIL REC'VD 5/5/2025 RETURN TO SENDER VACANT UNABLE TO FORWARD