



1129 HORNE RD - RESIDENTIAL STRUCTURE

- Substandard case started 6/11/2024.

Structure deemed substandard based on the following findings:

- Structure does not meet the minimum requirements and standards as set forth in the International Property Maintenance Code.
- Exterior structure is not in good repair, is not structurally sound, and does not prevent the elements or rodents from entering the structure.
- Interior of the structure is not in good repair, is not structurally sound, and is not in a sanitary condition.
- Structure is unfit for human occupancy and found to be dangerous to the life, health, and safety of the public.

City Recommendation: Demolition of residential structure (Building Survey attached)

Property located in a residential area and a main thoroughfare street. (Horne Rd)

According to NCAD, Jessica Olmos took possession of property 9/27/2019.

Case, Abatement, and Citation History

Total number of Code complaints: 2

Total number of cases: 13

Owner Compliance: 2

City Abatements: 9

Citations issued: 9



1129 HORNE RD - RESIDENTIAL STRUCTURE

Date	Case Type	Violation(s)	Status
07/01/2025	Vacant Building	Tall weeds, litter and solid waste and sidewalks, curbs and gutters	In progress
01/10/2025	Unsecure Vacant Building	Unsecured windows	Abated by City
06/20/2024	Vacant Building	Vacant Building	Expired
06/12/2024	Substandard Structure	Main structure unfit for human occupancy	In Progress
06/22/2023	Unsecure Vacant Building	Unsecure widows and door	Expired
06/22/2023	Vacant Building	Tall weeds, litter and solid waste and sidewalks, curbs and gutters	Expired
06/08/2021	Vacant building	Tall weeds, litter and solid waste and sidewalks, curbs and gutters	Expired
01/30/2020	Unsecured Vacant Building	Unsecured windows	Expired
01/30/2020	Vacant Building	Litter and solid waste	Expired
09/26/2019	Vacant Building	Tall weeds, litter and solid waste and sidewalks, curbs and gutters	Expired
02/01/2019	Care of premises	Tall weeds, litter and solid waste and sidewalks, curbs and gutters	Expired
08/14/2013	Care of premises	Tall weeds, litter and solid waste and sidewalks, curbs and gutters	Expired
06/04/2012	Vacant Building	Tall weeds, litter and solid waste and sidewalks, curbs and gutters	Expired



1129 HORNE RD - RESIDENTIAL STRUCTURE

Abatement history for 1129 Horne Rd.

<u>Date</u>	<u>Cost/Admin Fee</u>	<u>Case Type</u>
1. 02/28/2025	\$330/\$174	Secure Openings
2. 05/27/2025	\$80/\$125	Mowing and Cleaning
3. 02/28/2025	\$211.80/\$125	Mowing and Cleaning
4. 10/10/2024	\$192.86/\$125	Mowing and Cleaning
5. 02/28/2024	\$370/\$174	Secure Openings
6. 03/27/2024	\$190/\$174	Secure Openings
7. 06/20/2024	\$100/\$174	Secure Openings
8. 05/14/2024	\$192.86/\$125	Mowing and Cleaning
9. 02/26/2024	\$167.40/125	Mowing and Cleaning

Total: \$3155.92

CCPD calls to property:

Nature of Call	1129 Horne Rd.
Burglary In Progress	1
Burglary Not In Progress	1
Burglary Open Door or Window Possible Burglary	1
Disturbance In Progress	1
Disturbance Weapons Involved	1
Law Enforcement Investigation Field Event	1
Suspicious Circumstance(s) In Progress	1
Suspicious or Unusual Suspicious Person or Persons	1
Suspicious or Unusual Suspicious Vehicle	1
Trespassing Violation In Progress	1
Grand Total	10



1129 HORNE RD - RESIDENTIAL STRUCTURE

Attempted contact with Property Owner(s)

DATE	NAME	CONTACT DETAILS
01/10/2025	Jessica Olmos	On this day Code Compliance Officer Melanie Flores spoke with the owner about violations of tall weeds on the property and mentioned to her that we had a substandard case for the property. She told Melanie that there was a fire in 2019 but the property was secured, and it wasn't an issue
01/23/2025	Jessica Olmos	Code Officer Diana T Garza attempted contact. Left voicemail *
01/28/2025	Jessica Olmos	Code Officer Diana T Garza attempted contact. Left voicemail *
4/21/2025	Jessica Olmos	Code Officer Grace Elledge attempted contact. Left voicemail *
07/01/2025	Jessica Olmos	I called owner Jessica Olmos (361) 232-3685 and left voicemail to return my call. she called back. I informed her that I was moving forward with the case and what her intentions were with the property. She stated that she plans to fix it and that there is no fire damage in the interior of the structure. I told her about the upcoming BSB board meeting and encouraged her to attend so she can explain her intentions to the board members. She asked me if she needed to bring her lawyer. I told her that that was her decision. I told her I will let her know when the notice for the BSB board meeting is going out and remind her of the day and time of meeting. She also verified her mailing address was correct. No further incident
07/07/2025	Jessica Olmos	Text message was sent letting owner know about Hearing on July 24. She replied, "Okay, Thank you "

*For Clarification we had a one wrong number on the marked dates. We called (361) 232-2685. The Correct number is (361) 232-3685

COMPLAINT

Monday June 30,2025

Building Standards Board
City of Corpus Christi
2406 Leopard St.
Corpus Christi, Texas 78408

RE: 1129 HORNE RD

Case # V124811-061224

OWNER: Olmos Jessica

**Code Compliance Supervisor
Roland Maldonado**


Dear Board Members:

Pursuant to Article II and in accordance with Section 13-22(B), of the Corpus Christi Property Maintenance Code, this Department has initiated and prepared the above listed case for your review and consideration. On **February 27, 2025**, the code official determined that there were reasonable grounds to believe there was a violation(s) of the Corpus Christi Property Maintenance Code or any rule or regulation concerning the health, safety, or general welfare adopted by the city as it relates to structures or premises and gave notice of such alleged violation to the owner of the property. Thirty days have elapsed since the notice of violation(s) was provided and such violation(s) have not been cured.

Staff recommends a hearing be set for not less than ten (10) days or more than forty-five (45) days from the date of this complaint. At this hearing staff recommendation for the above listed property will be repair/**demolition**.

If you have any questions concerning the above, please call (361) 826-3046.

Roland Maldonado
Supervisor
Development Services
Code Compliance Division



cc: Carlos Martinez, John Solberg, Merced V. Pena, William B. Ewing Jr,
Chic G. Henderson, Lynne Hurlburt

6/30/2025

Code Compliance Supervisor: Roland Maldonado

Case# V234811-061224

Property Owner: OLMOS JESSICA

Address (☒Residential ☐Commercial): 1129 Horne Rd

Staff Recommendation(s): **Demolition**

☒Residential Structure only

☐Residential and Accessory Structure

☐Commercial Structure only

☐Commercial and Accessory Structure

Under the provisions of Section 13-22 (H)(1)(c) of the Corpus Christi Property Maintenance Code and due to substandard and dilapidated condition of the structure(s), a hazard to the health, safety, and welfare of the public is henceforth declared.

Therefore, the owner be required to **demolish** the structure(s) within thirty (30) days. If demolition is not started and completed as required, then the City be authorized to demolish.

Notices


1. Letters of substandard conditions sent by certified mail.
2. Final notice sent by certified mail.
3. Certified letter of hearing sent by certified mail
4. Notice of hearing published in newspaper.

Additional

1. Owner Deceased: ☒ No ☐ Yes If deceased verification by: ☐Obituary ☐Death Certificate
2. Structure Entered by: ☒Search Warrant ☐Consent Given by: Owner ☐Unsecure
3. Taxes due: ☐ Current ☒Past due -Amount owed: \$7,327.33
4. Utilities: ☐Active ☒Inactive-Last active date: 6/13/2019
5. Year Structure Built: 1950
6. Lawsuits: ☐Yes ☒No
7. Code Enforcement Maintaining Property: ☒Yes ☐No

CASE TIMELINE FOR 1129 HORNE


Activity	Date	Legal Requirement	Legal Reference
Code Enforcement Notified of Potential Violation	6/11/2024	n/a	n/a
Initial Inspection Completed	6/11/2024	When building, structure or premise thought to be substandard	Corpus Christi Property Maintenance Code 104.2
Notice of Violation Mailed to Last Known Addresses	3/4/2025	When there are reasonable grounds to believe there is a violation	City Ordinance Sec. 13-22(A) & (D)(2)
Notice of Violation Posted in Newspaper	5/16/2025 & 5/19/2025	When owner is unknown, whereabouts unknown, or where service of notice has failed (Published twice w/in a 10 day period)	City Ordinance Sec.13-22(A) & (D)(3)
Deadline to comply with Newspaper Notice of Violation	6/17/2025	When 30 days have elapsed from the date of first publication	City Ordinance Sec. 13-22(B)
Notice Received	6/20/2025	Return mail rec/vd 6/20/24 return to sender, vacant, unable to forward	n/a
Returned Notice of Violation Posted at Front Door of Property	5/27/25-5/30/25 & 6/2/25-6/6/25	When notice is returned showing unclaimed or not delivered	City Ordinance Sec. 13-22(A) & (D)(4)
Deadline to comply with Mailed Notice of Violation	4/5/2025	30 days from receipt of the notice	City Ordinance Sec. 13-22(A)(5)
Re-inspection	6/23/2025	Not less thans 30 days from receipt of the notice or when 30 days have elapsed from date of first publication	City Ordinance Sec. 13-22(B)
Complaint filed with BSB	6/30/2025	When owner refused to comply; when not cured within 30 days from receipt of notice or any further agreed time; or when 30 days have elapsed from date of first publication	City Ordinance Sec. 13-22(B)(2)
Notice of Hearing Mailed to Last Known Address	7/1/2025	At least 10 days prior to hearing	City Ordinance Sec. 13-22(C) & (D)(2)
Notice of Hearing Posted in Newspaper	6/30/2025 & 7/1/2025	At least 10 days prior to hearing when owner is unknown, whereabouts unknown, or where service of notice has failed (Published twice w/in a 10 day period)	City Ordinance Sec.13-22(C) & (D)(3)
Notice of Hearing Filed with County Clerk	7/1/2025	At least 10 days prior to hearing	City Ordinance Sec. 13-22(C) & Tx Local Gov't Code 214.001€
Returned Notice of Hearing Posted at Front Door of Property	7/14/25-7/18/25 & 7/21/25-7/23/25	When notice is returned showing unclaimed or not delivered	City Ordinance Sec. 13-22(C) & (D)(4)
BSB Agenda Posted	7/18/2025	72 hours (3 days) before scheduled time of hearing	Texas Govt. Code 551.043(a)
BSB Hearing	7/24/2025	Not less than 10 days nor more than 45 days after Complaint filed	City Ordinance Sec. 13-22 (C)







1129 HORNE




Aerial View











City of Corpus Christi – BUILDING SURVEY

Account Number: 4100-0001-0090

Inspection Date: 6/11/2024

Zoning Use: RS-6

Revised Date: 02/27/2025

Officer: Diana T Garza

Property Address: 1129 HORNE RD

FIRE DAMAGE TO REAR OF STRUCTURE

Legal Description: LAGUNA ACRES E/2 OF LT 9 BK 1

Owner: OLMOS JESSICA

Mail to: 313 INDIANA AVE

City, State, Zip: CORPUS CHRISTI, TX 78404-1714

☒ Dwelling ☐ Commercial ☐ Accessory ☐ Sq. Ft. 1 ☐ Story
☒ Wood Frame ☐ Masonry ☒ Fire Damage ☐ # of Units ☒ Inside Inspection
☒ Vacant ☐ Occupied ☒ Open ☒ Placard
Placard Posted on: 2/27/2025

Corrections must be made to the item(s) checked below to comply with the Corpus Christi Property Maintenance Code and/or ordinances of the City of Corpus Christi. The following city ordinances are applicable: Building, Plumbing, Electrical, Mechanical, Fire, Health and Zoning.

Permits Required:

☐ Building ☐ Plumbing ☐ Electrical ☐ Mechanical
☐ Fire ☐ Health ☐ Other:

Smoke Alarms:

☐ Missing ☐ Inoperative ☐ Improperly Located ☐ Additional Alarms Required

OUTSIDE WALL:

(304.1, 304.2 304.4 & 304.6)

Type:

☒ Charred Wood
☒ Rotten Wood
☒ Rotten Corner Boards
☐ Missing Boards
☐ Badly in Need of Paint
☒ Siding Broken / Missing
☐ Holes
☐ Cracks
☐ Buckled
☐ Leans
☐ Missing Brick
☐ Loose Brick
☒ Damaged Exterior Trim
☐ Other:

ROOF:

(304.1 & 304.7)

Type:

☒ Charred Wood
☒ Rotten Eaves
☐ Rotten Rafter Tails
☐ Rotten Decking
☒ Missing Shingles
☒ Deteriorated Shingles
☐ Leaks
☐ Sags
☐ Buckled
☐ Collapsed
☐ Worn
☐ Torn
☒ Holes
☐ Other:

FOUNDATION:

(304.1, 304.4 & 304.5)

Type:

☐ Inadequate Support
☐ Rotten Wood
☐ Piers Lean
☐ Piers Missing
☐ Cracks/Perimeter Wall
☐ Cracks/Slab
☐ Pads Missing/Cracked
☐ Missing Skirting
☐ Missing Access Cover
☐ Exposed Sills
☐ Rotten Sills
☐ Damaged Floor Joist
☐ Sagging Floor Joist
☐ Other:

WINDOWS: (304.1, 304.2 304.13,
304.13.1, 304.13.2, 304.14 &
304.17)

☒ Charred Wood
☒ Broken Glass
☐ Missing Screens
☐ Torn Screens
☐ Missing / Broken Sash
☐ Do Not Open
☒ Rotten Sills
☒ Rotten / Broken Frames
☐ Other:

PORCHES: (304.1, 304.2, 304.10,
304.12, 305.4, 305.5 & 307.1)

☐ Charred Wood
☐ Missing / Broken Boards
☐ Loose
☐ Rotten Wood
☒ Inadequate Support
☐ Support Post Missing
☐ Support Post Loose
☐ Faulty Weather Protection
☐ Other:

DOORS: (304.1, 304.2, 304.13,
304.14, 304.15, 304.16, 304.18,
305.6 & 702.1)

☐ Charred Wood
☐ Missing
☒ Damaged
☐ Poor Fit
☐ Damaged / Missing Screen(s)
☐ Off Hinges
☐ Blocked Exit
☒ Rotten
☐ Other:

STEPS: (304.1, 304.2
304.10, 304.12, 305.4 & 305.5)

☐ Charred Wood
☐ Rotten Wood
☐ Missing Boards
☒ Inadequate Support
☐ Missing Handrails
☐ Faulty Weather Protection
☐ Other:

PLUMBING: BATHTUB / SHOWER

(403.2, 502.1, 502.2, 502.3, 504.1, 504.2, 504.3, 505.1.1,
& 505.3)

☐ Missing
☐ Faucets Loose / Broken / Missing
☐ No Anti-Siphon Faucets
☐ Missing Overflow Plate
☐ Missing Tap
☐ Missing Shower Head
☐ Not Vented
☒ Disconnected
☐ Stopped Up
☐ Damaged Shower Stall
☐ Other:

PLUMBING: WATER CLOSET

(404.4.3, 502.1, 502.2, 502.3, 502.4, 503.1, 503.4,
504.1, 504.2, 504.3, 505.1.1, 506.1 & 506.2)

☐ Missing
☐ No Anti-Siphon Ballcock
☐ Stopped Up
☐ Poorly Anchored
☐ Seeps Around Bowl
☐ Water Supply Line Leaks
☐ Flush Ell Leaks
☐ Runs Constantly
☐ Tank Broken / Cracked
☐ Bowl Broken / Cracked
☒ Disconnected
☐ Missing Flush Handle
☐ Missing Flapper
☐ Urinal; No Back-Flow Preventive
☐ No Elongated Bowl / Open-end Seat
☐ Other:

WATER HEATER:

(505.4, 603.1, 603.2, 603.3, 603.4 603.5 & 603.6)

☐ Gas
☐ Electric
☐ Missing
☒ Disconnected
☐ Temperature Pressure Release Valve Missing
☐ Temperature Pressure Release Valve Broken
☐ Drain Line Missing
☐ Not Approved Pipe
☐ Not Extended Outside
☐ Elbowed Down
☐ Vent Missing / Loose
☐ No Double Wall Pipe / Attic
☐ Nonconforming Vent
☐ Inadequate Combustion Air
☐ Thermostat Missing / Damaged
☐ No Gas Cut Off
☐ Missing Firebox Door
☐ Gas Supply Line Not Approved Pipe
☐ Gas Fired – Located in Bathroom
☐ Gas Fired – Located in Bedroom
☐ Fire Damaged
☐ Other:

LAVATORY: (404.4.3, 502.1, 502.2, 502.3
502.4, 504.1, 504.2, 504.3, 505.1.1,
506.1 & 506.2)

- ☐ Missing
- ☐ No Anti-Siphon Faucets
- ☐ Faucets Leak / Broken / Missing
- ☐ "P" Trap Leaks / Missing
- ☐ Defective Trap
- ☐ Stopped Up
- ☐ Water Supply Line Leak
- ☐ Loose from Wall
- ☐ Nonconforming Waste Line
- ☒ Disconnected
- ☐ Other:

KITCHEN SINK: (305.1, 305.3, 502.1,
505.1.1, 506.1 & 506.2)

- ☐ Defective Trap
- ☐ Faucets Loose / Broken
- ☐ Faucets Missing
- ☐ "P" Trap Rubber Hose
- ☐ Trap Leaks / Missing
- ☐ Stopped Up
- ☒ Disconnected
- ☐ Damaged Counter Top
- ☐ Damaged Back Splash
- ☐ Other:

ELECTRICAL SERVICE: (604.1, 604.2
604.3, 604.3.1, 604.3.1.1, 604.3.2, 604.3.2.1
605.1, 605.2 & 605.3)

- ☐ Service Panel Burned
- ☐ Service Missing
- ☐ Service Appears Below Code
- ☐ Two-Wire Service
- ☐ Inadequate
- ☐ Defective
- ☒ Disconnected
- ☐ Service Not Grounded
- ☐ Missing Breakers / Fuses
- ☐ Missing Interior / Exterior Panel Cover
- ☐ Exposed Wiring
- ☐ Nonconforming Wiring in Panel
- ☐ Drops Too Low
- ☐ Other:

GAS SYSTEM: (602.1, 602.2, 602.3, 602.5
603.1, 603.2, 603.3, 603.4, 603.5 & 603.6)

- ☐ Gas Pressure Test Required
- ☐ Gas Leak
- ☐ Line Appears to Enter Building Below Grade Level
- ☐ Gas Supply Not Approved Pipe
- ☐ Rubber Hose to Space Heaters
- ☐ Non-Rigid Pipe Run Through Partition Wall
- ☐ Other:

PLUMBING MISCELLANEOUS:

(504.1, 504.2, 504.3, 505.3, 506.2 & 507.1)

- ☐ Open Clean Out / Water Leak; Yard / Under House
- ☐ Vent Stack Missing / Broken
- ☐ Vent Stack Not Extended Through Roof
- ☐ Rain Guard Damaged / Missing
- ☐ Exposed Exterior PVC Pipe
- ☐ PVC Water Supply Lines
- ☐ Washer No "P" Trap / Not Vented / Not Cut Offs
- ☐ Sewer Line Stopped Up
- ☐ Sewer Running Out on Ground
- ☐ Other:

INSIDE WALLS AND CEILINGS:

(305.1, 305.2, 305.3 & 404.3)

- ☒ Charred Wood
- ☐ Paint Deteriorated
- ☐ Cracks
- ☐ Holes
- ☐ Torn Wallpaper
- ☐ Damaged Paneling
- ☒ Sheetrock Broken / Missing / Holes, 506.1 & 506.2
- ☒ Sheetrock Mildewed / Buckled
- ☒ Ceiling Damaged / Missing
- ☐ Water Damaged / Smoke Damaged
- ☐ Impervious Material Around Tub
- ☐ Enclosure Damaged / Missing
- ☐ Walls Around Tub Not Water Resistant
- ☐ Inadequate Ceiling Height
- ☐ Other:

SYSTEM:

(604.3.2, 604.3.2.1, 605.1, 605.2 & 605.3)

- ☒ Burned Wiring / Plugs / Switches
- ☒ Burned Fixtures
- ☐ Less Than 1 Duplex Recept. /20 liner ft-
- ☐ Bedroom/Living Rm/Dining Rm/Den/Kitchen
- ☐ No Small Appliance Circuits Over Kitchen
- ☐ Counter Space with GFCI
- ☐ Only One Small Appliance Circuit Over Kitchen
- ☐ Counter Space with NO GFCI
- ☐ Kitchen Appliance Circuits – No GFCI
- ☒ Plugs Missing / Loose / Broken
- ☒ Switches Missing / Loose / Broken
- ☒ Fixtures Missing / Loose / Broken
- ☒ Missing Switch Cover / Plug Covers
- ☐ Extension Cords in Place of Permanent Wiring
- ☐ Bathroom Circuit NO GFCI
- ☐ Conduit Broken / Loose / Missing
- ☐ No Separate Circuit For
- ☐ No Disconnect for Air Conditioner
- ☐ Exterior Lights Missing; Front / Back / Side
- ☐ Porch Lights Broken / Missing / Loose
- ☐ Other:

INTERIOR FLOORS:

(305.1, 305.2, 305.3 & 305.4)

- ☐ Charred Wood
- ☒ Rotten Wood
- ☐ Missing Boards
- ☐ Holes
- ☐ Cracks
- ☐ Not Level
- ☒ Buckled
- ☐ Torn
- ☐ Damaged
- ☐ Other:

MECHANICAL:

(403.1, 403.2, 603.1 & 603.6)

- ☐ Vented Wall Heater Damaged / Missing
- ☐ Floor Furnace Damaged / Missing
- ☐ Nonconforming Gas Line to Space Heater
- ☐ Wall Heater with No Vent in Bathroom
- ☐ Thermostat Damaged / Missing
- ☐ Gas-Fired Heating Appliance within 2' of
- ☐ Tub / Shower / Water Closet
- ☐ Condensing Unit Damaged / Missing
- ☐ No Vent Fan or Window in Bathroom
- ☐ Vent Fan Missing / Not Operable
- ☐ Heat with No Vent in Commercial Building
- ☐ Fire Damage
- ☐ Other:

ACCESSORY SURVEY:

(302.7, 304.1, 304.2, 304.4, 304.5, 304.6 & 305.2)

- TYPE: _____
- ☐ Roof Type:
- ☐ Rotten
- ☐ Loose
- ☐ Torn
- ☐ Holes
- ☐ Missing
- ☐ Walls Type:
- ☐ Rotten
- ☐ Leaning
- ☐ Buckled
- ☐ Missing
- ☐ Other:

UNSANITARY CONDITIONS:

(308.3, 309.1, 504.1 & 505.1.2)

- ☐ No Hot and Cold Water Supply
- ☐ Insect, Roach, Rodent Infestation
- ☐ Lacks Adequate Garbage Containers
- ☐ Other:

- ☐ Foundation Type:
- ☐ Sunken
- ☐ Rotten Sills
- ☐ Other:

VIOLATION(S): 1129 HORNE RD

108.1.3 Structure unfit for human occupancy. A structure is unfit for human occupancy whenever the code official finds that such structure is unsafe, unlawful or, because of the degree to which the structure is in disrepair or lacks maintenance, is insanitary, vermin or rat infested, contains filth and contamination, or lacks ventilation, illumination, sanitary or heating facilities or other essential equipment required by this code, or because the location of the structure constitutes a hazard to the occupants of the structure or to the public.

304.1 General. The exterior of a structure shall be maintained in good repair, structurally sound and sanitary so as not to pose a threat to the public health, safety or welfare.

304.15 Doors. Exterior doors, door assemblies, operator systems if provided, and hardware shall be maintained in good condition. Locks at all entrances to dwelling units and sleeping units shall tightly secure the door. Locks on means of egress doors shall be in accordance with Section 702.3.

304.6 Exterior walls. Exterior walls shall be free from holes, breaks, and loose or rotting materials; and maintained weatherproof and properly surface coated where required to prevent deterioration.

304.7 Roofs and drainage. The roof and flashing shall be sound, tight and not have defects that admit rain. Roof drainage shall be adequate to prevent dampness or deterioration in the walls or interior portion of the structure. Roof drains, gutters and downspouts shall be maintained in good repair and free from obstructions. Roof water shall not be discharged in a manner that creates a public nuisance.

305.1 General. The interior of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. Occupants shall keep that part of the structure which they occupy or control in a clean and sanitary condition. Every owner of a structure containing a rooming house, housekeeping units, a hotel, a dormitory, two or more dwelling units or two or more nonresidential occupancies, shall maintain, in a clean and sanitary condition, the shared or public areas of the structure and exterior property.

305.6 Interior doors. Every interior door shall fit reasonably well within its frame and shall be capable of being opened and closed by being properly and securely attached to jambs, headers or tracks as intended by the manufacturer of the attachment hardware.

307.1 General. Every exterior and interior flight of stairs having more than four risers shall have a handrail on one side of the stair and every open portion of a stair, landing, balcony, porch, deck, ramp or other walking surface which is more than 30 inches (762 mm) above the floor or grade below shall have guards. Handrails shall not be less than 30 inches (762 mm) in height or more than 42 inches (1067 mm) in height measured vertically above the nosing of the tread or above the finished floor of the landing or walking surfaces. Guards shall not be less than 30 inches (762 mm) in height above the floor of the landing, balcony, porch, deck, or ramp or other walking surface.

Exception: Guards shall not be required where exempted by the adopted building code.

504.1 General. Plumbing fixtures shall be properly installed and maintained in working order, and shall be kept free from obstructions, leaks and defects and be capable of performing the function for which such plumbing fixtures are designed. Plumbing fixtures shall be maintained in a safe, sanitary and functional condition.

505.1 General. Every sink, lavatory, bathtub or shower, drinking fountain, toilet or other plumbing fixture shall be properly connected to either a public water system or to an approved private water system. Kitchen sinks, lavatories, laundry facilities, bathtubs and showers shall be supplied with hot or tempered and cold running water in accordance with the International Plumbing Code as adopted and amended by the City.

Exceptions: Facilities constructed lawfully without hot water.

505.1.2 Hot and Cold Water Supply: All kitchen sinks, lavatories, laundry facilities, bathtubs and showers shall be supplied with hot or tempered and cold running water in accordance with the International Plumbing Code as adopted and amended by the City.

Exceptions: Facilities constructed lawfully without hot water.

602.3 Heat supply. Every owner and operator of any building who rents, leases or lets one or more dwelling units or sleeping units on terms, either expressed or implied, to furnish heat to the occupants thereof shall supply heat to maintain a minimum temperature of 68°F (20°C) in all habitable rooms, bathrooms and toilet rooms. Exception: 1. When the outdoor temperature is below the winter outdoor design temperature for the locality, maintenance of the minimum room temperature shall not be required provide that the heating system is operating at its full design capacity. The winter outdoor design temperature for the locality shall be as indicated in Appendix D of the International Plumbing Code as adopted and amended by the City.

2. In areas where the average monthly temperature is above 30°F (-1°C), a minimum temperature of 65°F (18°C) shall be maintained.

604.2 Service. The size and usage of appliances and equipment shall serve as a basis for determining the need for additional facilities in accordance with NFPA 70. Dwelling units shall be served by a three-wire, 120/240 volt, single-phase electrical service having a minimum rating of 60 amperes. Exception: Electric service may be maintained if installed lawfully.

605.1 Installation. Electrical equipment, wiring and appliances shall be properly installed and maintained in a safe and approved manner.

605.2 Receptacles. Every habitable space in a dwelling shall contain not less than two separate and remote receptacle outlets. Every laundry area shall contain not less than one grounding-type receptacle or a receptacle with a ground fault circuit interrupter. Every bathroom shall contain not less than one receptacle. Any new bathroom receptacle outlet shall have ground fault circuit interrupter protection. All receptacle outlets shall have the appropriate faceplate cover for the location.



CASE DOCUMENTATION FOR VIOLATION LETTERS MAILED FOR BSB HEARING
[ALL LETTERS ARE MAILED CERTIFIED AND FIRST CLASS]

Case No: B1 Letters, V124811-061224

ADDRESS: 1129 HORNE RD

Tax Account No: 4100-0001-0090

Owner(s): JESSICA OLMOS

LAST UPDATED ON: Monday, March 24, 2025

LETTERS MAILED from 3/4/2025-3/4/2025

MAILED TO	ASSOCIATION WITH PROPERTY	RETURNED MAIL NOTES
JESSICA OLMOS 313 INDIANA AVE CORPUS CHRISTI TX 78404-1714	Owner	B1 Letter Mailed on 3/4/2025 RETURN MAIL REC'VD 3/24/2025 RETURN TO SENDER UNCLAIMED UNABLE TO FORWARD
JESSICA OLMOS 1129 HORNE RD CORPUS CHRISTI TX 78416	Owner	B1 Letter Mailed on 3/4/2025 RETURN MAIL REC'VD 3/13/2025 RETURN TO SENDER NOT DELIVERBALE AS ADDRESSED UNABLE TO FORWARD