






CONSTRUCTION PROGRESS PHOTOS





- Construction of Walls and Decks





- Installation of Cable Tray Supports and Upper Walkways and Decks



Secondary Clarifiers



- Construction of Interior Weir Troughs and Installation of Clarifier No. 2 Equipment






- Construction of Walkways and Decks Adjacent to UV Channels



Aerated Sludge Basins




- Installation of Process Piping and Electrical Conduits






Sludge Dewatering Building



- Construction of Walls and Decks




Electrical Control Room No. 1



- Installation of Blower Equipment and Electrical Conduits






Electrical Control Room No. 2




- Installation of Brick Veneer and Blower Equipment





Electrical Control Room No. 3




- Installation Electrical Equipment and Transformers






Administration/O&M Building



- Construction of Upper Occupied Deck







Solids Handling Odor Control



- Odor Control System Slab Completed





- Prepare Sub Grade for Retaining Walls, Generator Equipment On-Site





carollo
Engineers...Working Wonders With Water™

LNV
engineers | architects | contractors



City of Corpus Christi
WASTE WATER
DEPARTMENT