ATTACHMENT O Photos of Deteriorating Condensate Return Stations

Condensate Return Station #15 – Engine Test Cell Mechanical Room






Condensate Return Station #6 – Mechanical Room





Condensate Return Station #5 – Cowling Shop Mechanical Room





Condensate Return Station #13

