

#### 2119 HOWARD ST.- RESIDENTIAL STRUCTURE

Substandard case started 11/15/2024.

Structure deemed substandard based on the following findings:

- Structure does not meet the minimum requirements and standards as set forth in the International Property Maintenance Code.
- Exterior structure is not in good repair, is not structurally sound, and does not prevent the elements or rodents from entering the structure.
- Interior of the structure is not in good repair, is not structurally sound, and is not in a sanitary condition.
- Structure is unfit for human occupancy and found to be dangerous to the life, health, and safety of the public.

City Recommendation: Demolition of the residential structure (Building Survey attached)

Property located in a residential area and backs up to a City Park/Recreation Center.

According to NCAD, the owner Jimmy Luis Galvan took possession of the property 8/15/2007.

## Case, Abatement, and Citation History

Total number of Code complaints: 1

Total number of cases: 1

Owner Compliance: 0

City Abatements: 0

Citations issued: 0



## 2119 HOWARD ST.- RESIDENTIAL STRUCTURE

| Date     | Case Type   | Violation(s)                | Status      |
|----------|-------------|-----------------------------|-------------|
| 11/15/24 | Substandard | 108.1.5 Dangerous Structure | In Progress |
|          | Structure   | or Premises                 | -           |

# Abatement history for 2119 Howard St.

<u>Date</u>

Cost/Admin Fee

Case Type

No abatements have occurred at the property.

# CCPD calls to property:

| Nature of Call                                     | 2119 Howard St. |
|--|-----------------|
| Disturbance In Progress                            | 2               |
| EMS Request/Medical Emergency Choking Victim       | 1               |
| Forensic Services Request Recovered Stolen Vehicle | 1               |
| Law Enforcement Investigation Field Event          | 1               |
| LE Assist Assist to Pick Up Property               | 1               |
| Theft of Property or Services Not In Progress      | 2               |
| Grand Total  | 8               |

# Attempted contact with Property Owner(s)

| DATE     | NAME                | CONTACT DETAILS                      |  |
|----------|---------------------|--------------------------------------|--|
| 11/18/24 | DID NOT GIVE ME HER | 11/18/2024 @ 8:57AM, THE DAUGHTER OF |  |
|          | NAME                | THE PROPERTY OWNER CALLED (361-      |  |
|          |                     | 759-0870), SHE DID NOT GIVE ME HER   |  |
|          |                     | NAME BUT SAID THAT SHE SAW THE       |  |
|          |                     | PLACARD ON THE STRUCTURE, SHE        |  |
|          |                     | WAS VERY UPSET. SHE ALSO STATED      |  |
|          |                     | THAT SHE WOULD LIKE TO BE CALLED     |  |
|          |                     | IF THERE WERE ANY UPDATES OR         |  |
|          |                     | CHANGES.                             |  |
| 2/12/25  | AMY GALVAN          | 2/12/25 @ 2:57PM, THE DAUGHTER OF    |  |
|          |                     | THE PROPERTY OWNER, AMY GALVAN       |  |



# 2119 HOWARD ST.- RESIDENTIAL STRUCTURE

|         |                | (361-759-0870) CALLED ME BACK AND      |
|---------|----------------|--|
|         |                | STATED THAT HER MOTHER WILL BE         |
|         |                | GETTING THE DEMOLITION PERMIT          |
|         |                | TOMORROW.                              |
| 2/17/25 | PROPERTY OWNER | 2-17-25 @ 2:05PM, THE PROPERTY         |
|         |                | OWNER 956-533-0109, CALLED AND         |
|         |                | STATED THAT HE WILL BE PULLING A       |
|         |                | PERMIT TO DEMOLISH THE STRUCTURE.      |
| 5-9-25  | NELLY PEREZ    | 5-9-25 @ 11:29AM, I CALLED NELLY (361- |
|         |                | 742-2198), DAUGHTER OF THE PROPERTY    |
|         |                | OWNER AND SHE STATED THAT THEY         |
|         |                | PULLED A DEMO PERMIT BACK ON 2-18-     |
|         |                | 25. THE COMPANY THAT THEY WANTED       |
|         |                | TO DEMOLISH THE HOUSE IS HAVING        |
|         |                | ISSUES WITH THE MACHINERY, SO NOW      |
|         |                | THEY WANT THE CITY TO COMPLETE         |
|         |                | THE DEMOLITION AND THEY WOULD          |
| 1       |                | LIKE TO PAY THE CITY FEE IN            |
|         |                | INSTALLMENTS.                          |
|         |                |  |

| 4/28/2025  |   |   |                                |  |  |
|--|---|---|--------------------------------|--|--|
| Code Compliance Supervisor: Roland Maldonado   |   |   |                                |  |  |
| Case# \  | Case# V247986-111524  |   |                                |  |  |
| Propert  | erty Owner: Jimmy Luis Galvan   |   |                                |  |  |
| Addres   | ress ( Residential Commercial): 2119 Howard   | St.   |                                |  |  |
| Staff Re   | Recommendation(s): Demolition   |   |                                |  |  |
| ⊠Resid   | esidential Structure only   | al and Accessory Structure  |                                |  |  |
| Com  | ommercial Structure only  | ial and Accessory Structure   | е                              |  |  |
|  |   |   |                                |  |  |
| due to   | er the provisions of Section 13-22 (H)(1)(c) of the C<br>to substandard and dilapidated condition of the str<br>are of the public is henceforth declared. |   |                                |  |  |
| Therefore, the owner be required to <b>demolish</b> the structure(s) within thirty (30) days. If demolition is not started and completed as required, then the City be authorized to demolish. |   |   |                                |  |  |
| Notices  | <u>ces</u>  |   |                                |  |  |
| 1.<br>2.<br>3.<br>4.   | <ol> <li>Final notice sent by certified mail.</li> <li>Certified letter of hearing sent by certified mail</li> </ol>                                      | ied mail.   |                                |  |  |
| Additio  | tional  |   |                                |  |  |
| 1.<br>2.<br>3.<br>4.<br>5.<br>6.   | 3. Taxes due: □ Current □ Past due -Amou 4. Utilities: □ Active □ Inactive-Last act 5. Year Structure Built: 1939 6. Lawsuits: □ Yes □ No                 | nsent Given by: Owner<br>Int owed: \$708.07<br>Live date: 8/25/2021 | □ Death Certificate □ Unsecure |  |  |
|  |   |   |                                |  |  |

#### **COMPLAINT**

Monday, April 28, 2025

Building Standards Board City of Corpus Christi 2406 Leopard St. Corpus Christi, Texas 78408

RE: 2119 Howard St.

Case # V247986-111524

**OWNER: Jimmy Luis Galvan** 

Code Compliance Supervisor Roland Maldonado

#### Dear Board Members:

Pursuant to Article II and in accordance with Section 13-22(B), of the Corpus Christi Property Maintenance Code, this Department has initiated and prepared the above listed case for your review and consideration. On **November 15, 2024**, the code official determined that there were reasonable grounds to believe there was a violation(s) of the Corpus Christi Property Maintenance Code or any rule or regulation concerning the health, safety, or general welfare adopted by the city as it relates to structures or premises and gave notice of such alleged violation to the owner of the property. Thirty days have elapsed since the notice of violation(s) was provided and such violation(s) have not been cured.

Staff recommends a hearing be set for not less than ten (10) days or more than forty-five (45) days from the date of this complaint. At this hearing staff recommendation for the above listed property will be repair/demolition.

If you have any questions concerning the above, please call (361) 826-3046.


Roland Maldonado

Supervisor

Development Services Code Compliance Division

cc: Carlos Martinez, John Solberg, Merced V. Pena, William B. Ewing Jr, Chic G. Henderson, Lynne Hurlburt

| CASE TIMELINE FOR 2119 HOWARD ST.  |                   |  |   |  |
|--|-------------------|--|---|--|
| Activity   | Date              | Legal Requirement  | Legal Reference                                   |  |
| Code Enforcement Notified of   | 11/15/2024        |  |   |  |
| Potential Violation  | 11/15/2024        | n/a  | n/a   |  |
| Initial Inspection Completed   |                   | When building, structure or premise                      | Corpus Christi Property                           |  |
|  | 11/15/2024        | thought to be substandard                                | Maintenance Code 104.2                            |  |
| Notice of Violation Mailed to Last   |                   | When there are reasonable grounds to                     | City Ordinance                                    |  |
| Known Addresses  | 2/13/2025         | believe there is a violation                             | Sec. 13-22(A) & (D)(2)                            |  |
| Notice of Violation Posted in  |                   | When owner is unknown, whereabouts                       | City Ordinance Sec.13-                            |  |
| Newspaper  | 3/14/2025 &       | unknown, or where service of notice has                  | 22(A) & (D)(3)                                    |  |
|  | 3/17/2025         | failed (Published twice w/in a 10 day period)            |   |  |
| Deadline to comply with Newspaper  |                   | When 30 days have elapsed from the date                  | City Ordinance                                    |  |
| Notice of Violation  | 4/13/2025         | of first publication                                     | Sec. 13-22(B)                                     |  |
| Notice Received  |                   | Returned mail rec'd-Return to sender,                    | n/a   |  |
|  | 2/19/2025         | attempted not known, unable to forward                   | ,   |  |
| Returned Notice of Violation Posted at   | 3/24/25-3/28/25 & | When notice is returned showing                          | City Ordinance                                    |  |
| Front Door of Property   | 3/31/25-4/4/25    | unclaimed or not delivered                               | Sec. 13-22(A) & (D)(4)                            |  |
| Deadline to comply with Mailed Notice  |                   | 30 days from receipt of the notice                       | City Ordinance                                    |  |
| of Violation   | 3/14/2025         | 30 days from receipt of the notice                       | Sec. 13-22(A)(5)                                  |  |
| Re-inspection  |                   | Not less thans 30 days from receipt of the               | City Ordinance                                    |  |
|  | 4/23/2025         | notice or when 30 days have elapsed from                 |   |  |
|  | , = ,             | date of first publication                                | · ·   |  |
| Complaint filed with BSB   |                   | When owner refused to comply; when                       | City Ordinance                                    |  |
|  |                   | not cured within 30 days from receipt of                 | Sec. 13-22(B)(2)                                  |  |
|  | 4/28/2025         | notice or any further agreed time; or                    |   |  |
|  |                   | when 30 days have elapsed from date of first publication |   |  |
| Notice of Hearing Mailed to Last   |                   | At least 10 days prior to hearing                        | City Ordinance                                    |  |
| Known Address  | 4/29/2025         |  | Sec. 13-22(C) & (D)(2)                            |  |
|  | 1, 23, 2023       |  |   |  |
| Notice of Hearing Posted in Newspaper  |                   | At least 10 days prior to hearing when                   | City Ordinance Sec. 13-                           |  |
|  | 4/28/2025 &       | owner is unknown, whereabouts                            | 22(C) & (D)(3)                                    |  |
|  | 4/29/2025         | unknown, or where service of notice has                  |   |  |
|  | 4,23,2023         | failed (Published twice w/in a 10 day                    |   |  |
| National Control of the Control of t |                   | period)  | City Ondings C- 42                                |  |
| Notice of Hearing Filed with County  | 4/29/2025         | At least 10 days prior to hearing                        | City Ordinance Sec. 13-<br>22(C) & Tx Local Gov't |  |
| Clerk 4/29/2025  |                   |  | Code 214.001€                                     |  |
| Returned Notice of Hearing Posted at   | 5/12/25-5/16/25 & | When notice is returned showing                          | City Ordinance                                    |  |
| Front Door of Property   | 5/19/25-5/21/25   | unclaimed or not delivered                               | Sec. 13-22(C) & (D)(4)                            |  |
| BSB Agenda Posted  |                   | 72 hours (3 days) before scheduled time                  | Texas Govt. Code                                  |  |
|  | 5/16/2025         | of hearing   | 551.043(a)  |  |
| BSB Hearing  |                   | Not less than 10 days nor more than 45                   | City Ordinance                                    |  |
|  | 5/22/2025         | days after Complaint filed                               | Sec. 13-22 (C)                                    |  |



# 2119 HOWARD ST

Aerial View






























# City of Corpus Christi – BUILDING SURVEY

| _                |  |                                      |   |                  |                                     |  |
|------------------|--|--------------------------------------|---|------------------|-------------------------------------|--|
| Account N        | Number: 200061118  |                                      |   |                  |                                     |  |
| Inspection       | n Date: 11/15/2024   |                                      |   |                  |                                     |  |
| Zoning Us        | se: RM-3   |                                      |   |                  |                                     |  |
| Revised D        | Date: 2/12/2025  |                                      |   |                  |                                     |  |
| Officer: M       | IICHAEL GUTIERREZ  | 7                                    |   |                  |                                     |  |
|                  |  |                                      |   |                  |                                     |  |
|                  | Address: 2119 HOWA   |                                      |   |                  |                                     |  |
| Legal Des        | scription: WILBURN L   | T 4 BK 2                             |   |                  |                                     |  |
| Owner: JI        | IMMY LUIS GALVAN   |                                      |   |                  |                                     |  |
| Mail to: 2       | 18 SPRUCE  |                                      |   |                  |                                     |  |
| City, State      | e, Zip: CORPUS CHR   | ISTI, TX 78408                       |   |                  |                                     |  |
|                  |  |                                      |   |                  |                                     |  |
| <u>X</u> W       | welling<br>lood Frame<br>acant<br>osted on:                    | _Commercial<br>_Masonry<br>_Occupied | AccessoryFire DamageOpen                          | 1,765_<br>1<br>X | _Sq. Ft.<br>_# of Units<br>_Placard | 1Story XInside Inspectio                       |
|                  | Required:  | Plumbing                             | Electrical  |                  | Mechanical                          |  |
| Fi               |  | _Health                              | Other:  |                  |                                     |  |
| Smoke Al         | arms:  |                                      |   |                  |                                     |  |
| M                | lissing  | _Inoperative                         | Improperly Lo                                     | cated            | Addit                               | ional Alarms Required                          |
| (3<br>T <u>y</u> | UTSIDE WALL:<br>304.1, 304.2 304.4 & 30<br>ype:<br>harred Wood | D4.6)<br>                            | ROOF:<br>(304.1 & 304.7)<br>Type:<br>Charred Wood |                  | (304.<br>Type:                      | NDATION:<br>1, 304.4 & 304.5)<br>quate Support |
|                  | otten Wood   | X                                    |   |                  |                                     | n Wood   |
|                  | otten Corner Boards<br>lissing Boards                          |                                      | Rotten Rafter Tails<br>Rotten Decking             |                  | Piers                               | Lean<br>Missing                                |
|                  | adly in Need of Paint  | X                                    | Missing Shingles                                  |                  |                                     | s/Perimeter Wall                               |
|                  | iding Broken / Missing   | X                                    | Deteriorated Shingles                             |                  |                                     | s/Slab   |
|                  | oles   | X                                    | Leaks   |                  |                                     | Missing/Cracked                                |
|                  | racks  | Χ                                    | Sags  |                  |                                     | ng Skirting                                    |
|                  | uckled   | X                                    | Buckled   |                  |                                     | ng Access Cover                                |
|                  | eans   | X                                    | Collapsed   |                  |                                     | sed Sills                                      |
|                  | lissing Brick  | x                                    | Worn  |                  |                                     | n Sills  |
|                  | oose Brick   | x                                    | Torn  |                  |                                     | nged Floor Joist                               |
|                  | amaged Exterior Trim   | x                                    | Holes   |                  |                                     | ing Floor Joist                                |
|                  | ther:  | ^                                    | Other:  |                  | Other                               |  |
|                  |  |                                      |   |                  |                                     |  |

|          | WINDOWS: (304.1, 304.2 304.13,                                       | PORCHES: (304.1, 304.2, 304.10  | DOORS: (304.1, 304.2, 304.13,              |
|----------|--|---------------------------------|--|
|          | 304.13.1, 304.13.2, 304.14 &   | 304.12, 305.4, 305.5 & 307.1)   | 304.14, 304.15, 304.16, 304.18,            |
|          | 304.17)  | ,                               | 305.6 & 702.1)                             |
|          | Charred Wood   | Charred Wood                    | Charred Wood                               |
| X        | Broken Glass   | Missing / Broken Boards         | Missing                                    |
| Χ        | Missing Screens  | Loose                           | Damaged                                    |
|          | Torn Screens   | Rotten Wood                     | Poor Fit                                   |
|          | Missing / Broken Sash  | Inadequate Support              | Damaged / Missing Screen(s)                |
|          | Do Not Open  | Support Post Missing            | Off Hinges                                 |
| Χ        | Rotten Sills   | Support Post Loose              | Blocked Exit                               |
|          | Rotten / Broken Frames   | Faulty Weather Protection       | Rotten                                     |
| -        | Other:   | Other:                          | Other:                                     |
|          | STEPS: (304.1, 304.2   | PLUMBING: BA                    | THTUB / SHOWER                             |
|          | 304.10, 304.12, 305.4 & 305.5)                                       | (403.2, 502.1, 50               | 02.2, 502.3, 504.1, 504.2, 504.3, 505.1.1, |
|          |  | & 505.3)                        |  |
|          | Charred Wood   | XMissing                        |  |
|          | Rotten Wood  | Faucets Loose /                 | Broken / Missing                           |
|          | Missing Boards   | No Anti-Siphon                  | Faucets                                    |
|          | Inadequate Support   | Missing Overflow                | w Plate                                    |
| <u>X</u> | Missing Handrails  | Missing Tap                     |  |
|          | Faulty Weather Protection  | Missing Shower                  | Head                                       |
|          | Other:   | Not Vented                      |  |
|          |  | Disconnected                    |  |
|          |  | Stopped Up                      |  |
|          |  | Damaged Show                    | er Stall                                   |
|          |  | Other:                          |  |
|          | PLUMBING: WATER CLOSET   | WATER HEATE                     | R:   |
|          | (404.4.3, 502.1, 502.2, 502.3, 502.4, 5                              |                                 | 03.2, 603.3, 603.4 603.5 & 603.6)          |
|          | 504.1, 504.2, 504.3, 505.1.1, 506.1 &                                |                                 |  |
| <u>X</u> | Missing  | Gas                             |  |
|          | No Anti-Siphon Ballcock  | Electric                        |  |
|          | Stopped Up   | XMissing                        |  |
|          | Poorly Anchored  | Disconnected                    | B. I                                       |
|          | Seeps Around Bowl  |                                 | essure Release Valve Missing               |
|          | Water Supply Line Leaks  |                                 | essure Release Valve Broken                |
| -        | Flush Ell Leaks  | Drain Line Missi                |  |
|          | Runs Constantly  | Not Approved P                  |  |
|          | Tank Broken / Cracked  | Not Extended O                  | utside                                     |
| -        | Bowl Broken / Cracked  | Elbowed Down                    |  |
| -        | Disconnected   | Vent Missing / L                |  |
|          | Missing Flush Handle   | No Double Wall                  | •  |
|          | Missing Flapper  | Nonconforming                   |  |
| -        | Urinal; No Back-Flow Preventive<br>No Elongated Bowl / Open-end Seat | Inadequate Con                  |  |
|          | Other:   | Thermostat Miss No Gas Cut Off  | sing / Damageu                             |
|          | ould.  |                                 | Door                                       |
|          |  | Missing Firebox                 |  |
|          |  |                                 | e Not Approved Pipe<br>ated in Bathroom    |
|          |  |                                 | ated in Battiroom                          |
|          |  | Gas Filed = Loc<br>Fire Damaged | ated in Deditorii                          |
|          |  | r ile Damageu                   |  |

|          | <b>LAVATORY:</b> (404.4.3, 502.1, 502.2, 502.3 502.4, 504.1, 504.2, 504.3, 505.1.1, 506.1 & 506.2) |   | <b>GAS SYSTEM:</b> (602.1, 602.2, 602.3, 602.5 603.1, 603.2, 603.3, 603.4, 603.5 & 603.6) |
|----------|--|---|---|
| Χ        | Missing  |   | Gas Pressure Test Required  |
|          | No Anti-Siphon Faucets   |   | Gas Leak  |
|          | No Ami-Siphon Faddets<br>Faucets Leak / Broken / Missing   | - | Cas Leak<br>Line Appears to Enter Building Below Grade Level                              |
|          | addeds Leak / Blokell / Wilssing<br>"P" Trap Leaks / Missing                                       | - | Cine Appears to Enter building below Grade LevelGas Supply Not Approved Pipe              |
|          | Defective Trap   |   | Gas Supply Not Approved Fipe<br>Rubber Hose to Space Heaters                              |
|          | Stopped Up   | - | Non-Rigid Pipe Run Through Partition Wall   |
|          | Stopped Op<br>Water Supply Line Leak   | - |   |
|          | Loose from Wall  | - | Other: PULLED METER   |
|          |  |   |   |
|          | Nonconforming Waste Line   |   |   |
|          | Disconnected   |   |   |
|          | Other:   |   |   |
|          | KITCHEN SINK: (305.1, 305.3, 502.1,  |   | PLUMBING MISCELLANEOUS:   |
|          | 505.1.1, 506.1 & 506.2)  |   | (504.1, 504.2, 504.3, 505.3, 506.2 & 507.1)   |
|          | Defective Trap   |   | Open Clean Out / Water Leak; Yard / Under House   |
|          | Faucets Loose / Broken   |   | Vent Stack Missing / Broken   |
|          | Faucets Missing  |   | Vent Stack Not Extended Through Roof  |
|          | "P" Trap Rubber Hose   |   | Rain Guard Damaged / Missing  |
|          | Trap Leaks / Missing   |   | Exposed Exterior PVC Pipe   |
|          | Stopped Up   | _ | PVC Water Supply Lines  |
|          | Disconnected   |   | Washer No "P" Trap / Not Vented / Not Cut Offs  |
|          | Damaged Countertop   |   | Sewer Line Stopped Up   |
|          | Damaged Back Splash  |   | Sewer Running Out on Ground   |
|          | Other:   | - | Other:  |
|          | ELECTRICAL SERVICE: (604.1, 604.2  |   | INSIDE WALLS AND CEILINGS:  |
|          | 604.3, 604.3.1, 604.3.1.1, 604.3.2, 604.3.2.1  |   | (305.1, 305.2, 305.3 & 404.3)   |
|          | 605.1, 605.2 & 605.3)  |   |   |
|          | Service Panel Burned   |   | Charred Wood  |
|          | Service Missing  |   | Paint Deteriorated  |
|          | Service Appears Below Code   | X | Cracks  |
|          | Two-Wire Service   | X | Holes   |
|          | Inadequate   |   | Torn Wallpaper  |
|          | Defective  |   | Damaged Paneling  |
| <u>X</u> | Disconnected   | X | Sheetrock Broken / Missing / Holes, 506.1 & 506.2   |
|          | Service Not Grounded   |   | Sheetrock Mildewed / Buckled  |
|          | Missing Breakers / Fuses   | X | Ceiling Damaged / Missing   |
|          | Missing Interior / Exterior Panel Cover  | X | Water Damaged / Smoke Damaged   |
|          | Exposed Wiring   |   | Impervious Material Around Tub  |
|          | Nonconforming Wiring in Panel  |   | Enclosure Damaged / Missing   |
|          | Drops Too Low  |   | Walls Around Tub Not Water Resistant  |
|          | Other:   |   | Inadequate Ceiling Height   |
|          |  |   | Other:  |

|          | SYSTEM:  | INTERIOR FLOORS:                                   |
|----------|--|--|
|          | (604.3.2. 604.3.2.1, 605.1, 605.2 & 605.3)         | (305.1, 305.2, 305.3 & 305.4)                      |
|          | Burned Wiring / Plugs / Switches                   | Charred Wood                                       |
|          | Burned Fixtures                                    | Rotten Wood  |
|          | Less Than 1 Duplex Recept. /20 liner ft-           | Missing Boards                                     |
|          | Bedroom/Living Rm/Dining Rm/Den/Kitchen            | Holes  |
|          | No Small Appliance Circuits Over Kitchen           | Cracks   |
|          | Counter Space with GFCI                            | Not Level  |
|          | Only One Small Appliance Circuit Over Kitchen      | Buckled  |
|          | Counter Space with NO GFCI                         | Torn   |
|          | Kitchen Appliance Circuits – No GFCI               | XDamaged   |
|          | Plugs Missing / Loose / Broken                     | Other:   |
|          | Switches Missing / Loose / Broken                  |  |
|          | Fixtures Missing / Loose / Broken                  |  |
|          | Missing Switch Cover / Plug Covers                 |  |
|          | Extension Cords in Place of Permanent Wiring       |  |
|          | Bathroom Circuit NO GFCI                           |  |
|          | Conduit Broken / Loose / Missing                   |  |
|          | No Separate Circuit For                            |  |
|          | No Disconnect for Air Conditioner                  |  |
|          | Exterior Lights Missing; Front / Back / Side Porch | Lights Broken / Missing / Loose                    |
|          | Other:   |  |
|          | <del></del>  |  |
|          |  |  |
|          | MECHANICAL:  | ACCESSORY SURVEY:                                  |
|          | (403.1, 403.2, 603.1 & 603.6)                      | (302.7, 304.1, 304.2, 304.4, 304.5, 304.6 & 305.2) |
| ·        | Vented Wall Heater Damaged / Missing               | TYPE: NONE   |
|          | Floor Furnace Damaged / Missing                    | Roof Type:   |
|          | Nonconforming Gas Line to Space Heater             | Rotten   |
|          | Wall Heater with No Vent in Bathroom               | Loose  |
| -        | Thermostat Damaged / Missing                       | Torn   |
|          | Gas-Fired Heating Appliance within 2' of           | Holes  |
| A        | Tub / Shower / Water Closet                        | Missing  |
|          | Condensing Unit Damaged / Missing                  |  |
|          | No Vent Fan or Window in Bathroom                  | Walls Type:  |
| 0        | Vent Fan Missing / Not Operable                    | Rotten   |
| 8        | Heat with No Vent in Commercial Building           | Leaning  |
|          | Fire Damage  | Buckled  |
|          | Other:   | Missing  |
|          |  | Other:   |
|          | UNSANITARY CONDITIONS:                             |  |
|          | (308.3, 309.1, 504.1 & 505.1.2)                    | Foundation Type:                                   |
| <u>X</u> | No Hot and Cold-Water Supply                       | Sunken   |
|          | Insect, Roach, Rodent Infestation                  | Rotten Sills                                       |
|          | Lacks Adequate Garbage Containers                  | Other:   |
|          | Other:   |  |

#### VIOLATION(S): 2119 HOWARD ST.

- 108.1.5 Dangerous structure or premises. For the purpose of this code, any structure or premises that has any or all of the conditions or defects described below, but which is not limited to those described below, shall be considered dangerous and may be deemed substandard:
- 1. Any door, aisle, passageway, stairway, exit or other means of egress that does not conform to the approved building or fire code of this City as related to the requirements for existing buildings.
- 2. The walking surface of any aisle, passageway, stairway, exit or other means of egress is so warped, worn loose, torn or otherwise unsafe as to not provide safe and adequate means of egress.
- 3. Any portion of a building, structure or appurtenance that has been damaged by fire, earthquake, wind, flood, deterioration, neglect, abandonment, vandalism or by any other cause to such an extent that it is likely to partially or completely collapse, or to become detached or dislodged, or which cannot be expected to withstand winds of hurricane force.
- 4. Any portion of a building, or any member, appurtenance or ornamentation on the exterior thereof that is not of sufficient strength or stability, or is not so anchored, attached or fastened in place so as to be capable of resisting natural or artificial loads of one and one-half the original designed value.
- 5. The building or structure, or part of the building or structure, because of dilapidation, deterioration, decay, faulty construction, the removal or movement of some portion of the ground necessary for the support, or for any other reason, is likely to partially or completely collapse, or some portion of the foundation or underpinning of the building or structure is likely to fail or give way.
- 6. The building or structure, or any portion thereof, is clearly unsafe for its use and occupancy.
- 7. The building or structure is neglected, damaged, dilapidated, unsecured or abandoned so as to become an attractive nuisance to children who might play in the building or structure to their danger, becomes a harbor for vagrants, criminals or immoral persons, or enables persons to resort to the building or structure for committing a nuisance or an unlawful act.
- 8. Any building or structure has been constructed, exists or is maintained in violation of any specific requirement or prohibition applicable to such building or structure provided by the approved building or fire code of the jurisdiction, or of any law or ordinance to such an extent as to present either a substantial risk of fire, building collapse or any other threat to life and safety.
- 9. A building or structure, used or intended to be used for dwelling purposes, because of inadequate maintenance, dilapidation, decay, damage, faulty construction or arrangement, inadequate light. Ventilation, electrical, mechanical, or plumbing system, or otherwise, is determined by the code official to be unsanitary, unfit for human habitation or in such a condition that is likely to cause sickness or disease, including all conditions conducive to the harboring of rats or mice or other disease-carrying animals or insects reasonably calculated to spread disease.
- 10. Any building or structure, because of a lack of sufficient or proper fire- resistance-rated construction, fire protection systems, electrical system, fuel connections, mechanical system, plumbing system or other cause, is determined by the code official to be a threat to life or health.
- 11. All buildings or structures which have pit privies where the same are not permitted by law or which are not connected to the city sewer when required by law or where inadequate and unsanitary pit privies or septic tanks exist.
- 12. Any portion of a building remains on a site after the demolition or destruction of the building or structure or whenever any building or structure is abandoned so as to constitute such building or portion thereof as an attractive nuisance or hazard to the public.
- 304.1 General. The exterior of a structure shall be maintained in good repair, structurally sound and sanitary so as not to pose a threat to the public health, safety or welfare.

  \*\*\*
- 304.12 Handrails and guards. Every handrail and guard shall be firmly fastened and capable of supporting normally imposed loads and shall be maintained in good condition.
- 304.13 Window, skylight and door frames. Every window, skylight, door and frame shall be kept in sound condition, good repair and weather tight.
- "304.14 Insect screens. Every door, window and other outside opening required for ventilation of habitable rooms, food preparation areas, food service areas or any areas where products to be included

or utilized in food for human consumption are processed, manufactured, packaged or stored shall be supplied with approved tightly fitting screens of minimum 16 mesh per inch (16 mesh per 25 mm), and every screen door used for insect control shall have a self-closing device in good working condition. Exceptions: (1) Screens shall not be required where other approved means, such as air curtains or insect repellent fans, are employed. (2) Habitable spaces served by air conditioning unit in sound condition and good repair. (3) Doors are not required to be screened if there is an additional ventilation source in the room.

\*\*\*

304.15 Doors. Exterior doors, door assemblies, operator systems if provided, and hardware shall be maintained in good condition. Locks at all entrances to dwelling units and sleeping units shall tightly secure the door. Locks on means of egress doors shall be in accordance with Section 702.3.

304.6 Exterior walls. Exterior walls shall be free from holes, breaks, and loose or rotting materials; and maintained weatherproof and properly surface coated where required to prevent deterioration.

304.7 Roofs and drainage. The roof and flashing shall be sound, tight and not have defects that admit rain. Roof drainage shall be adequate to prevent dampness or deterioration in the walls or interior portion of the structure. Roof drains, gutters and downspouts shall be maintained in good repair and free from obstructions. Roof water shall not be discharged in a manner that creates a public nuisance.

305.6 Interior doors. Every interior door shall fit reasonably well within its frame and shall be capable of being opened and closed by being properly and securely attached to jambs, headers or tracks as intended by the manufacturer of the attachment hardware.

503.4 Floor surface. In other than dwelling units, every toilet room floor shall be maintained to be a smooth, hard, nonabsorbent surface to permit such floor to be easily kept in a clean and sanitary condition.

\*\*\*

504.1 General. Plumbing fixtures shall be properly installed and maintained in working order, and shall be kept free from obstructions, leaks and defects and be capable of performing the function for which such plumbing fixtures are designed. Plumbing fixtures shall be maintained in a safe, sanitary and functional condition.

\*\*\*

505.1 General. Every sink, lavatory, bathtub or shower, drinking fountain, toilet or other plumbing fixture shall be properly connected to either a public water system or to an approved private water system. Kitchen sinks, lavatories, laundry facilities, bathtubs and showers shall be supplied with hot or tempered and cold running water in accordance with the International Plumbing Code as adopted and amended by the City.

Exceptions: Facilities constructed lawfully without hot water.

602.3 Heat supply. Every owner and operator of any building who rents, leases or lets one or more dwelling units or sleeping units on terms, either expressed or implied, to furnish heat to the occupants thereof shall supply heat to maintain a minimum temperature of 68°F (20°C) in all habitable rooms, bathrooms and toilet rooms. Exception: 1. When the outdoor temperature is below the winter outdoor design temperature for the locality, maintenance of the minimum room temperature shall not be required provide that the heating system is operating at its full design capacity. The winter outdoor design temperature for the locality shall be as indicated in Appendix D of the International Plumbing Code as adopted and amended by the City.

2. In areas where the average monthly temperature is above 30°F (-1°C), a minimum temperature of 65°F (18°C) shall be maintained.

604.2 Service. The size and usage of appliances and equipment shall serve as a basis for determining the need for additional facilities in accordance with NFPA 70. Dwelling units shall be served by a three-wire, 120/240 volt, single-phase electrical service having a minimum rating of 60 amperes. Exception: Electric service may be maintained if installed lawfully.

\*\*\*

605.1 Installation. Electrical equipment, wiring and appliances shall be properly installed and maintained in a safe and approved manner.

605.2 Receptacles. Every habitable space in a dwelling shall contain not less than two separate and remote receptacle outlets. Every laundry area shall contain not less than one grounding-type receptacle or a receptacle with a ground fault circuit interrupter. Every bathroom shall contain not less than one receptacle. Any new bathroom receptacle outlet shall have ground fault circuit interrupter protection. All receptacle outlets shall have the appropriate faceplate cover for the location.



# CASE DOCUMENTATION FOR VIOLATION LETTERS MAILED FOR BSB HEARING [ALL LETTERS ARE MAILED CERTIFIED AND FIRST CLASS]

Case No: B1 Letters, V247986-111524

ADDRESS: 2119 HOWARD ST.

Tax Account No: 9640-0002-0040

Owner(s): JIMMY LUIS GALVAN

LAST UPDATED ON: Wednesday, March 12, 2025

## LETTERS MAILED from 2/13/2025-3/14/2025

| MAILED TO                      | ASSOCIATION WITH PROPERTY | RETURNED MAIL NOTES           |
|--------------------------------|---------------------------|-------------------------------|
| GALVAN JIMMY LUIS              | OWNER                     | B1 Letter Mailed on 2/13/2025 |
| 218 SPRUCE                     |                           |                               |
| CORPUS CHRISTI, TX. 78408      |                           |                               |
| GALVAN JIMMY LUIS              | OWNER                     | B1 Letter Mailed on 2/13/2025 |
| 2119 HOWARD ST.                |                           | RETURNED MAIL REC'D 2/19/25-  |
| CORPUS CHRISTI, TX. 78408      |                           | RETURN TO SENDER              |
|                                |                           | ATTEMPTED NOT KNOWN           |
|                                |                           | UNABLE TO FORWARD             |
| JIMMY LUIS GALVAN              | OWNER                     | B1 Letter Mailed on 3/14/2025 |
| 4706 ½ COVENTRY LN.            |                           | RETURNED MAIL REC'D 3/18/25-  |
| CORPUS CHRISTI, TX. 78411-4932 |                           | SIGNED BY ESTRADA             |