

#### Texas Water Development Board (TWDB) Groundwater Database (GWDB) Well Information Report for State Well Number 79-58-709



## GWDB Reports and Downloads

### Well Basic Details

#### **Scanned Documents**


State Well Number	7958709
County	San Patricio
River Basin	San Antonio-Nueces
Groundwater Management Area	16
Regional Water Planning Area	N - Coastal Bend
Groundwater Conservation District	San Patricio County GCD
Latitude (decimal degrees)	28.041389
Latitude (degrees minutes seconds)	28° 02' 29" N
Longitude (decimal degrees)	-97.860278
Longitude (degrees minutes seconds)	097° 51' 37" W
Coordinate Source	+/- 1 Second
Aquifer Code	121EVGL - Evangeline Aquifer
Aquifer	Gulf Coast
Aquifer Pick Method	
Land Surface Elevation (feet above sea level)	65
Land Surface Elevation Method	Interpolated From Topo Map
Well Depth (feet below land surface)	509
Well Depth Source	Person Other than Owner
Drilling Start Date	
Drilling End Date	6/0/1951
Drilling Method	
Borehole Completion	

Well Type	Withdrawal of Water
Well Use	Public Supply
Water Level Observation	Miscellaneous Measurements
Water Quality Available	No
Pump	Submersible
Pump Depth (feet below land surface)	
Power Type	Electric Motor
Annular Seal Method	
Surface Completion	
Owner	City of Corpus Christi C.C site No.4
Driller	Tom Carothers
Other Data Available	
Well Report Tracking Number	
Plugging Report Tracking Number	
U.S. Geological Survey Site Number	
Texas Commission on Environmental Quality Source Id	
Groundwater Conservation District Well Number	
Owner Well Number	
Other Well Number	
Previous State Well Number	
Reporting Agency	Texas Water Development Board
Created Date	
Last Update Date	

Reported flow 600 gpm. Remarks Casing - No Data Well Tests Test Date Test Type Yield (gallons per minute) Drawdown (ft.) **Test Hours** Unknown 600 Lithology - No Data Annular Seal Range - No Data Plugged Back - No Data Borehole - No Data Filter Pack - No Data Packers - No Data







Code		below land surface)	indicates rise in level	(ft. above sea level)					
Ρ	3/16/1988	-6.93		71.93	1	Texas Water Development Board	Pressure Gage		
Х	1/27/1989				1	Texas Water Development Board		27	
Х	12/14/1989				1	Texas Water Development Board		27	
Х	12/5/1991				1	Texas Water Development Board		27	

#### **Code Descriptions**

Status Code	Status Description	Remark ID	Remark Description
Р	Publishable	27	Well flowing and unable to shut-in
Х	No Measurement		





#### Water Quality Analysis - No Data Available

GWDB DISCLAIMER: Except where noted, all of the information provided in the Texas Water Development Board (TWDB) Groundwater Database (http://www.twdb.texas.gov/groundwater/data/gwdbrpt.asp) is believed to be accurate and reliable; however, the TWDB assumes no responsibility for any errors appearing in rules or otherwise. Further, TWDB assumes no responsibility for the use of the information provided. PLEASE NOTE that users of these data are responsible for checking the accuracy, completeness, currency and/or suitability of all information themselves. TWDB makes no guarantees or warranties as to the accuracy, completeness, currency, or suitability of the information provided via the Groundwater Database (GWDB). TWDB specifically disclaims any and all liability for any claims or damages that may result from providing GWDB data or the information. For additional information or answers to questions concerning the TWDB GWDB, contact the Groundwater Data Team at GroundwaterData@twdb.texas.gov.

21

**4** L,

WELL SUMMUNE         Austraction       Galiad [Th (202)         Field BD. /Americ Kell BD. Galiad [Th (202)         Field BD. /Americ Kell BD. Galiad [Th (202)]         States Wall BD. The State Sta	TEXAS WATER DEVELOPMENT I	BOARD -O-
Field No. Jonner's Well No. State CountySarRtricio(205)		
Field No. / Domer's Well No. Section	Outcrop: Qal - Allunum	WW 70 57 7.8
1. tocstion:i_ii_startionslockslocksurveytut_28 02 28, tong 2751 26 "         Pit-(512) = 882-3000         2. Dence:	Aquifer(s): (20/100/17/(284) Project No	$\frac{1}{4} = \frac{1000}{2} + 1000$
PH-(51) -880-3000 2. <u>Omer:</u> Gity of Carpus Christi Inderes: B. Boy 2077, Corpus Christi T. 787469 X Tenant (other) James L., Riky, P.E., deferes: Po. So 24. Sould a Jb 78602 Pd. Sol 49-24 britter: Torn Caroltars 1. Link Surface Elevation: 65. ft. above mol determined by 7/2 Dirk to D. Graphoic. Map 4. <u>priled:</u> 19.52; bug, Cable Toll (mear) Alr. 5. <u>borbic conjetion</u> : 9. T. Meas. 6. <u>Borehole conjetion</u> : 9. The series ft. 6. <u>Borehole conjetion</u> : 9. The series ft. 6. <u>Borehole conjetion</u> : 9. Jones Stating 315 ft. 6. <u>Borehole conjetion</u> : 9. Jones July 1. <u>Underseamed</u> , <u>fravel Packet</u> 7. <u>Pang</u> : Mr. 10. <u>Stages</u> Boyls Blamns. <u>setting</u> 315 ft. 10. <u>Marries Flows</u> , <u>friest</u> , <u>Jones</u> July 2. Jones J		
2. <u>Densr:</u> <u>Citr</u> <u>of</u> <u>Carpus</u> <u>Christi</u> <u>R</u> <u>777409</u> <b>X</b> <u>Teanant</u> (other) <u>Carpus</u> <u>L. Riky</u> <u>P.E.</u> <u>Address:</u> <u>P.D. Bay</u> <u>2017</u> <u>Corpus</u> <u>Christi</u> <u>R</u> <u>777409</u> <b>X</b> <u>Teanant</u> (other) <u>Carpus</u> <u>L. Riky</u> <u>P.E.</u> <u>Address:</u> <u>P.D. Bay</u> <u>2017</u> <u>Corpus</u> <u>Christi</u> <u>R</u> <u>777409</u> <b>X</b> <u>Teanant</u> <u>Carpus</u> <u>L. Riky</u> <u>P.E.</u> <u>Address:</u> <u>P.D. Bay</u> <u>2017</u> <u>Corpus</u> <u>Christi</u> <u>R</u> <u>777409</u> <b>X</b> <u>Teanant</u> <u>Carpus</u> <u>L. Riky</u> <u>P.E.</u> <u>Address:</u> <u>P.D. Bay</u> <u>2017</u> <u>Corpus</u> <u>Christi</u> <u>R</u> <u>777409</u> <b>X</b> <u>Teanant</u> <u>Carpus</u> <u>Large</u> <u>19</u> <u>22</u> <u>100</u> , <u>Cable</u> <u>Toth</u> <u>Matersi</u> <u>P.D. 90</u> <u>9000</u> <u>P.D. 9000</u> <u>9000</u> <u>P.D. 9000</u> <u>9000</u> <u>90000</u> <u>9000</u> <u>9000</u> <u>9000</u> <u>90000</u> <u>900000</u> <u>90000</u> <u>900000</u> <u>900000</u> <u>900000</u> <u>900000</u> <u>90000</u> <u>90000</u> <u>900000</u> <u>900000</u>	<pre>1. Location:t,t, Section, Block, Survey</pre>	, Lat. <u>28</u> _ <u>02</u> _28_, Long. 27° <u>5</u> 1_34
2. <u>Dener:</u> <u>City of Corpus Christi</u> <u>Maress</u> <u>P. 0. Boy 2017</u> Corpus Christi <u>F.</u> 277469 <b>X</b> Tranant (other) <u>Corpus L. Riky <u>P.E.</u> <u>Maressi</u> <u>P.C. 300 26</u> 2000.6 JB 703602 <u>PU Subscitute</u> <u>Maressi</u> Diffit Surface <u>Favation</u>: <u>65</u> <u>ft</u>: above mal determined by <u>7/2</u> <u>Drin.</u> <u>TD</u> <u>PD</u> <u>GROUPDic</u> <u>Map</u> <u>1. <u>Bidlister Eavation</u>: <u>655</u> <u>ft</u>: above mal determined by <u>7/2</u> <u>Drin.</u> <u>TD</u> <u>PD</u> <u>GROUPDic</u> <u>Map</u> <u>1. <u>Bidlister Eavation</u>: <u>655</u> <u>ft</u>: above mal determined by <u>7/2</u> <u>Drin.</u> <u>TD</u> <u>PD</u> <u>GROUPDic</u> <u>Map</u> <u>Maressi</u> <u>1. <u>Bidlister Eavation</u>: <u>655</u> <u>ft</u>: above mal determined by <u>7/2</u> <u>Drin.</u> <u>TD</u> <u>PD</u> <u>GROUPDic</u> <u>Map</u> <u>Map</u> <u>Maressi</u> <u>P. 2009</u> <u>Corpus <u>Subsci</u> <u>TD</u> <u>PD</u> <u>GROUPDic</u> <u>Map</u> <u>Map</u> <u>Maressi</u> <u>P. 2009</u> <u>Corpus <u>Subsci</u> <u>Transfit</u> <u>Maressi</u> <u>Production</u> <u>Ft</u>: <u>100 6000</u> <u>groupDic</u> <u>TD</u> <u>Ft</u> <u>Maressi</u> <u>Subsci</u> <u>Ft</u>. <u>8. betor</u>: <u>Mr</u>. <u>Free</u> <u>Free</u> <u>Free</u> <u>Maressi</u> <u>Production</u> <u>Ft</u>. <u>8. tetor</u>: <u>Mr</u>. <u>Free</u> <u>Bowles Diam</u> <u>Bowles <u>Production</u> <u>Ft</u>. <u>9. viald</u>: <u>Flow</u> <u>Corpus</u> <u>Pum</u> <u>Bowles <u>Production</u> <u>Ft</u>. <u>9. viald</u>: <u>Flow</u> <u>Corp</u> <u>Pum</u> <u>Bowles <u>Production</u> <u>Ft</u>. <u>Production</u> <u>Group</u> <u>Pum</u> <u>Bowles</u> <u>Production</u> <u>Ft</u>. <u>Production</u> <u>Group</u> <u>Pum</u> <u>Bowles</u> <u>Production</u> <u>Ft</u>. <u>Production</u> <u>Group</u> <u>Pum</u> <u>Bowles</u> <u>Production</u> <u>Ft</u>. <u>Production</u> <u>Baboratory</u> <u>TDS</u> <u>Sp</u> <u>Cond</u> <u>Done</u> <u>Production</u> <u>Marksi</u> <u>Coopticand Surface</u> <u>Marksi</u> <u>Production</u> <u>Marksi</u> <u>TD</u> </u></u></u></u></u></u></u></u></u></u></u></u></u>		
Deltie:	Ptt-(5.	12 -880-3000
Deltie:	2. Owner: City of Corpus Christien Address: P.O. BO	1x 9277, Corpus Christi Tx 78746 Seale Dam (Lake Carous Christi)
Deltie:	RX Tenant (other): James L., Kiby, F.E. Address: Po. Bo	28 5000 A TX 78302 Po: 512 57
4. <u>prilled:</u>		
4. <u>prilled:</u>	3. Land Surface Elevation:65ft. above ms1 determined by2 M	nin-topographic_Map
6. <u>porchole Completion</u> : Open Hole, Streight Wall, Underreamed, (ravel Packed) 7. <u>Pump</u> : Mfr	4. <u>Drilled:19_52;</u> Dug, Cable Tool, (Rotary) Air,	
6. <u>Borehole Completion</u> : Open Hole, Streight Well, Underreamed, (cravel Packed) 7. <u>Pump</u> : Mr		Cemented From ft. to ft
7. Puge       MP		Diam. Type Setting (feet)
Bit organ       10. http://withing.com/distribution/dist	7. Pump: NfrType Submersible	
Colum Diam	No. Stages, Bowls Diamin., Setting3!5ft.	
(s. Yield: Flow 600 gpm, Pumpgpm, Hees., (apt), EstDate3/16/84 10. Performance Test: DateLength of TestHade by	Column Diamin., Length Tallpipeft.	16 Oliver Sone
10. performance Test:       DeteLength of TestHade byft.         Static Levelft. Pumping Level 245 ft. Orm-downft.         Productiongom Specific Capacitygom/ft.         11. Quality: (Remarks on teste, odor, color, etc.)	8. <u>Motor</u> : MfrFuelHP60	_ `
Static Levelft. Pumping Level 265 ft. Drewnownft. Productiongam Specific Capacitygam/ft. 11. Quality: (Remarks on taste, odor, color, etc.) DateLaboratoryTDSSp Cond DateLaboratoryTDSSp Cond 12. Other data available (as circled): Pumping Test, Power & Yield Test, Drillers Log. Formation Samples, Geophysical Log(s)(type) 13. Water Level(s): +6 -93 ft. TestStation(type) 14. Use: Don., Stock, Public Supply Ind., Irr., Observation, Other (Test Hole, Oll Test, etc.) Public. Water Supply 15. Recorded by: Effic Adidas Dan Muller source of data: Observation and City Records Date:Itb(88 16. Remarks: Flaw MeterInstalled 17. Location or Sketch:Installed 18. Remarks: Flaw MeterInstalled 19. Location or Sketch:Installed 10. Location or Sketch:	( 9. <u>Yield</u> : Flow	16 88
Productiongpm Specific Capacitygpm/ft. 11. Quality: (Remarks on taste, odor, color, etc.) Analyses DateLaboratoryTDSSp Cond DateLaboratoryTDSSp Cond 12. Other data available (as circled): Pumping Test, Power & Yield Test, Drillers Log, Formation Samples, Geophysical Log(s)(type) 13. Water Level(s): + 6.93 ft. International Surface ft. Copp:Balovewhich isft. above Land Surface ft. Copp:Balovewhich isft. above Land Surface ft. Copp:Balovewhich isft. above Land Surface 14. Use: Dom., Stock, Cubilic Supply Ind., Irr., Observation, Other (Test Hole, Oll Test, etc.) Public Woter Supply 15. Recorded by: Eric Adidas Dan, Muller Source of data: Observation and City Records Date:Its 16. Remarks: Flow MeterInsta Lied . 17. Location or Sketch:Insta Lied . 18. We obs. Well	10. <u>Performance Test</u> : DateLength of TestMade by	
11. Quality: (Remarks on taste, odor, color, etc.)	Static Leveft. Pumping Level_245_ft. Drawdownft.	
Analyses DateLaboratoryTDSSp Cond DateLaboratoryTDSSp Cond 12. Other data available (as circled): Pumping Test, Power & Yield Test, Drillers Log, Formation Samples, Geophysical Log(s)(type) 13. Water Level(s):+6.93 ft. Cont11b1988 bove above pecture gaaquatich is _3.0 ft. below Land surface ft. rept19_above which isft. below Land surface ft. rept19_above which isft. below Land surface 14. Use: Dom., Stock, Public Supply Ind., Irr., Observation, Other (Test Hole, OII Test, etc.) Public Water Supply 15. Recorded by:Efic Adidas Dan Miller Source of data: Observation and City Records Date:I688 16. Remarks: Flaw Meter Installed. 17. Location or Sketch:	Productiongpm Specific Capacitygpm/ft.	
DateLaboratoryTDSSp Cond DateLaboratoryTDSSp Cond 12. Other data available (as circled): Pumping Test, Power & Yield Test, Drillers Log, Formation Samples, Geophysical Log(s)(type) 13. Water Level(s): + 6.93 ft. Tent3][b]19&8 bord obove pessing gaagiwhich is _3.0 ft. bove Land Surface ft. rept19 abovewhich isft. bove Land Surface ft. rept19 abovewhich isft. below Land Surface 14. Use: Dom., Stock, Public Supply Ind., Irr., Observation, Other (Test Hole, OII Test, etc.) Public Water Supply 15. Recorded by: Effic Adidas Dan Müller Source of data: Observation and City Records Date:Ib[88 16. Remarks: Flaw Meter installed. 17. Location or Sketch:	11. Quality: (Remarks on taste, odor, color, etc.)	
DateLaboratoryTDSSp Cond 12. Other data available (as circled): Pumping Test, Power & Yield Test, Drillers Log, Formation Samples, Geophysical Log(s)(type) 13. Water Level(s):+6.93 ft. rept. 14. Use: Dom., Stock, Public Supply) Ind., Irr., Observation, Other (Test Hole, Oll Test, etc.) Public. Water Supply 15. Recorded by:Efic Adidas Dan Muller source of data: Observation and Gty Records Date: 316/88 16. Remarks: Flow Meterinstalled. 17. Location or Sketch: 17. Location or Sketch: 17. Location or Sketch: 17. Location or Sketch: 18. Use: Donder Supply 19. Adida Supply Ind., Irr., Observation, Other (Test Hole, Oll Test, etc.) Public. 19. Jonathis 10. Jonathis 10. Jonathis 11. Location or Sketch: 11. Location or Sketch: 12. Jonathis 13. Jonathis 14. Use: Donder Supply 15. Records Date: Jieles 16. Remarks: Flow Meterinstalled. 17. Location or Sketch: 18. Jonathis 19. Jonathis 19. Jonathis 10. Jonathis 10. Jonathis 10. Jonathis 10. Jonathis 11. Jonathis 12. Jonathis 13. Jonathis 14. Jonathis 15. Jonathis 15. Jonathis 16. Remarks: Jieles 17. Jonathis 18. Jonathis 19. Jonathis 19. Jonathis 10. Jonathis 11. Jonathis 11. Jonathis 12. Jonathis 13. Jonathis 14. Jonathis 15. Jonathis 15. Jonathis 16. Jonathis 17. Jonathis 18. Jonathis	Analyses	
12. Other data available (as circled): Pumping Test, Power & Yield Test, Drillers Log, Formation Samples, Geophysical Log(s)	DateLaboratoryTDSSp Cond	
12. Other data available (as circled): Pumping Test, Power & Yield Test, Drillers Log, Formation Samples, Geophysical Log(s)	DateLaboratoryTDSSp Cond	
Formation Samples, Geophysical Log(s)		
13. <u>Hater Level(s): +6.93</u> ft. <u>meas</u> 3[16] 1988 <u>bore</u> above pressure gauge which is 3.0 ft. <u>below</u> land surface ft. <u>rept</u> 14. <u>Use</u> : Dom., Stock, Public Supply Ind., Irr., Observation, Other (Test Hole, Oll Test, etc.) <u>Public</u> (Water Supply 15. <u>Recorded by: Eric Adidas Dan Müller</u> source of data: Observation and City Records Date: 316/88 16. Remarks: Flaw <u>Meter</u> installed. 17. <u>Location or Sketch</u> : Contract to Uisit Well. 17. <u>Location or Sketch</u> : Contract to Uisit Well. 18. <u>Contract to Uisit Well</u> 19. <u>Contract to Uisit Well</u> 19. <u>Contract to Uisit Well</u> 10. <u>La Fruta</u> 10. <u>Kanging</u> 11. <u>Use</u> : W/L Obs. Well <u>W/Q Obs. Well</u>		
ft. rept:       19	(type)	above above
14. <u>Use</u> : Dom., Stock, Public Supply Ind., Irr., Observation, Other (Test Hole, OII Test, etc.) <u>Public Water Supply</u> 15. <u>Recorded by: Eric Adidas Dan Müller</u> source of data: <u>Observation and City Records Date:</u> <u>3</u> 16(88 e 16. <u>Remarks: Flow meter installed</u> . <b>*</b> <u>Contact to visit Well</u> . 17. <u>Location or Sketch</u> : <u>Contact to visit</u> <u>Contact to Contact</u> <u>Contact to visit</u> <u>Contact</u> <u>Contact to visit</u> <u>Contact</u> <u>Contac</u>	13. water Level (s) : 1 D 1 Tt. meas SILE 1904 Detowe Pestik	above Land Surface
15. <u>Recorded by: Eric Adidas/Dan Müller source of data: Observation and City Records Date: 3/16/88</u> e 16. Remarks: Flaw <u>meter installed</u> . * <u>Contact to visit Well</u> . 17. <u>Location or sketch:</u> y (contact to visit Well. 17. <u>Location or sketch:</u> y (contact to visit Well. UCCONTACT to visit Well. (contact to visit	<sup>ft.</sup> meas <sup>19</sup> below	Which ist. below Land Surrace
e 16. Remarks: Flow meter installed. * <u>Contact to visit well</u> . 17. Location or sketch: g (copps office	14. Use: Dom., Stock, Public Supply Ind., Irr., Observation, Other (Test Hole,	, oil Test, etc.) [ubic while supply
* <u>Contact to visit Well</u> . 17. <u>Location or Sketch:</u> 9 Contact to visit Well. 17. <u>Location or Sketch:</u> 9 Contact to visit Well. 9 Contact to visit to vi		
17. Location or Sketch: 9 (Copy) of the control of		
Fall Graging Station To Sandia W/L Obs. Well W/Q Obs. Well		
Fall Graging Station To Sandia W/L Obs. Well W/Q Obs. Well		
FAL To Sandia W/L Obs. Well W/Q Obs. Well	17. Location or sketch: A this of the and this	· See attached sketch
FAL To Sandia W/L Obs. Well	9 (Coling 1) + + + + + + + + + + + + + + + + + +	-@-
FAL To Sandia W/L Obs. Well	3 all the the La Fruita	
To Sandia W/L Obs. Well W/Q Obs. Well	Fall Gaging	
W/L Obs. Well W/Q Obs. Well	E Sandia	
	TWDB-0308 (Rev. 12-11-85)	W/L Obs. Well W/Q Obs. Well State Well No79 - 58 - 709

State Well No. 79 - 58-709



## WELL COMPLETION INFORMATION

CLIENT: City of Corpus Christi WELL NO: CC Site #4 DATE OF COMPLETION: 1952 (Approximate) TYPE OF COMPLETION: Gravel Pack DATUM: N/A TD: 509' (August 1984) PBTD:\_\_\_\_\_

CASING:

14

Size	Material	Setting
16"	Black Pipe	

SCREENS:

Size	Material	Setting	Openings
16"	Black Pipe		Mill Slot

79-58-709

# DAILY LOG

# CLIENT Corpus Christi Water Supply Study

WELL <u>CC Well #4 (at Lake)</u>

Ed L. Reed & Associates, Inc. Consulting Hydrologist Corpus Christi-Midland, Texas


BY Tom Carothers

2

4

		· · · · · · · · · · · · · · · · · · ·	
DATE	TIME	DEPTH	ACTIVITY
8/27/84	0830 to		Tom Carothers and Bob Richardson visited with Austin Nelson of
	1230		Corpus Christi and check sites of 4 city wells near the lake.
		· · · · · · · · · · · · · · · · · · ·	Two wells along N. shore of lake, 1 well at Sunrise Beach and
			1 well on city land below dam.
8/28/84	0830 to		City maintenance crew jack hammer concrete off Well #4 below
	1730		dam. Opened plate and jack hammer concrete at #3 Sunrise Beach
			well, this well still has junk. Opened Well #1 north along
· ·			lake with jack hammer. Well #2 not to be used, original pump
	·····		stuck in hole.
8/29/84	0830 to		City crew tries to open Well #3 at Sunrise Beach, still no luck
	1500		Cleared brush from Well #4 site.
8/31/84	0800 to		Richardson crew arrived and ran impressinon block in well. TD
[	1800		approximately 509' no obstruction evident. Test. Run, pump
			in hole on 27 joints of 10'. Problem with drive shaft and
			right angle drive when pump started.
	· · · · · · · · · · · · · · · · · · ·		
9/1/84	0830 to	- <u></u>	Richardson repaired pump, ran pumping test from 1,000' to
	1730		1,500' at rates from about 300 to 600 gpm. Water flowing
			approximately 53 minutes after shut down. Started pulling
			pump pipe after test.
		·	
9/4/84	0800 to	· · · · · · · · · · · · · · · · · ·	Finish pulling pump and begin move to Site #1.
	1100	l	
	· · ·		<sup>1</sup> → · · · · · · · · · · · · · · · · · ·
9/17/84			Pawlik installs 60 horse power submersible pump, 315' of column
	· · · · · · · · · · · · · · · · · · ·		pipe.
12/6/84	1507		PWL = 189.02' at 680 gpm 60 psi.
	· · · · · · · · · · · · · · · · · · ·		
12/12/84	1400		665 gpm.
	:		
		[	
	· · ·	<u>                                      </u>	
	·		
11		{	
		<b> </b>	
[		1	
		<u>†</u>	
L		£	

79-58-709



Below Dame Pp Rd 25

PUMP INFORMATION

City of Corpus Christi Info Pg 1 of 1

CLIENT: City of Corpus Christi WELL NO.: CC Site #4

PUMP

Туре:	Submersible
Brand:	Pioneer
Model:	UZ600-4A
Stages:	4A
Setting Depth:	315'
Column Pipe:	6" Galv Pipe
Curve:	Attached
Serial No.:	46955

#### MOTOR

Brand:	Franklin
HP:	60HP, 460V
Phase:	3 phase

# CONTROLS

METER

Brand:	Kent
Model:	
Size:	6"

September 17, 1984 (Pump replaced March 4, 1985) DATE INSTALLED: Pawlik Well Service Inc., George West, Texas PURCHASED FROM: INSTALLED BY: Pawlik Well Service Inc., George West, Texas